Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	WELL API NO. June 19, 2008
1625 N. French Dr , Hobbs, NM 88240 <u>District II</u>	OH CONSEDVATION DIVISION	30-025-12076
1301 W. Grand Ave, Artesia, NM	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	0 2010 Santa Fe, NM 87505	STATE S FEE S 6. State Oil & Gas Lease No.
1220 S St. Francis Dr , Santa Fe, NM	t in	B-8580
	SOCD ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		Rhodes Yates Unit
1. Type of Well: Oil Well Gas Well Other Injection		8. Well Number 3
2. Name of Operator		9. OGRID Number
B C Operating, Inc 3. Address of Operator		160825 10. Pool name or Wildcat
P O Box 50820 Midland, TX 79710		Rhodes Yates Seven Rivers
4. Well Location		
Unit Letter B: 660' feet from the North line and 1980' feet from the East line		
Section 28	Township 26S Range 37E 11. Elevation (Show whether DR, RKB, RT, GR, et	NMPM Lea County
CARLO CONTROL OF THE	11. Elevation (<i>Snow whether DR, RRB, R1, GR, et</i> 2967' DF	<i>e.</i>)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	PLUG AND ABANDON REMEDIAL WO	
		RILLING OPNS. P AND A
PULL OR ALTER CASING March March	MULTIPLE COMPL CASING/CEME	NT JOB
A COMMUNICACION		7 AND 100
OTHER 12 Parity	OTHER	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		- The state of the proposed completion
	Approved	d for plugging of well bore only. under bond is retained pending receipt
	of C-103	(Subsequent Report of Well Plugging)
	Forms, we	w be found at OCD Web Page under ww.cmnrd.state.nm.us/ocd.
1. RIH & set CIBP @ 3030', 35' cmt on top. 2. Perf @ 2845', pump 50 sx cmt, tag @ 2594'.		
3. Perf @ 1210', pump 30 sx cmt, tag @ 1003'.		
4. Perf @ 400', pump 30 sx cmt, tag @ 212'.		
 5. Perf @ 60', pump 30 sx cmt, fell back, pump 30 sx cmt, fell back. 6. Tag cmt @ 18', circulate 10 sx to surface. 		
	ors, install P&A marker, level & clean location.	4-12-10-P+A PerTP
Spud Date: 11/26/41	Rig Release Date: 7/29/42	
in the second second		the second second
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE TITLE Regulatory Analyst DATE 5/5/10		
Type or print name PHONE: (432) 684-9696		
For State Use Only		
APPROVED BY: TITLE STATE DATE 5-26-10		
APPROVED BY: DATE 5-26-10 Conditions of Approval (if any):		