Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ı
ACD HADDS	[
UCU-ESEPANA REPORT	ı Le
OCD-HOBBS	П

FORM APPROVED OMB NO. 1004-0135 Expires January 31, 2004

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	---------	-----	---------	----	-------

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals ANDREGUE

,	6.	If Indian, Allottee or Tribe Name	
ገ			

	,	1,100	PROPOR	<i>"</i>		
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No		
1 Type of Well Oil Well X Gas Well Other 2. Name of Operator ENERVEST OPERATING, L.L.C.	A	TIN: ERIDŒT HELF	RICH	8. Well Name and N H.M. ERITT 9. API Well No.	o. #13	
3a. Address		3b. Phone No. (include ai	rea code)	30-025-06000	✓	
1001 FANNIN ST., STE. 800, HOUSTON, TEXAS 77002 (713)659-3500			10. Field and Pool,	or Exploratory A	Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			EUNIC MONUMEN			
UNIT LETTER J 2,310' FSL & 1,650' FEL SEC. 07, T-20S, R-37E 12. CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF	NOTICE, REP	11. County or Paris LEA COUNTY ORT, OR OTHER	/ NM	<u></u>
TYPE OF SUBMISSION		TY	PE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Reclamation Recomples	te dy Abandon	Water Shut-Off Well Integrity Other	1
	i e					

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)
 - 1) SET 5-1/2" CIBP @ 3,430'; CIRC. WELL W/ PXA MUD; MIX X PUMP A 25 SX. CMT. PLUG @ 3,430'-3,230'.
 - 2) CUT X ATTEMPT TO PULL 5-1/2" CASING @ +/-3,000".
 - 3) MIX X PUMP A 35 SX. CMT. PLUG @ 3,050'-2,950' (5-1/2" CSG.STUB); WOC X TAG TOP OF CMT. PLUG.
 - 4) MIX X PUMP A 40 SX. CMT. PLUG @ 2,505'-2,405' (B/SALT); WOC X TAG TOP OF CMT. PLUG.
 - 5) MIX X PUMP A 40 SX. CMT. PLUG @ 1,155'-1,055' (T/SALT); WOC X TAG TOP OF CMT. PLUG.
 - 6) MIX X PUMP A 40 SX. CMT. PLUG @ 667'-567' (13-3/8" CSG.SHOE).
 - 7) MIX X CIRCULATE TO SURFACE A 20 SX. CMT. PLUG @ 63'-3'.
 - 8) DIG OUT X OUT OFF WELLHEAD 3' B.G.L.; WELD STEEL STEEL PLATE ON CASINGS X INSTALL DRY HOLE MARKER.

RECLAMATION PROCEDURE ATTACHED

SEE ATTACHED FOR CONDITIONS OF APPROVAL

I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title	
DAVID A. EYLER	AGENT	
Dan DA El	Date 04/13/10	APPROVED
THIS SPACE FOI	R FEDERAL OR STATE OFFICE US	E /s/ Roger Hall
Approved by	7.70 Title	MAY 2 2010
Conditions of approval, if any, are attached. Approval of this notice doe certify that the applicant holds legal or equitable title to those rights in which would entitle the applicant to conduct operations thereon.	s not warrant or Office	Petroleum Engineer
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it	t a crime for any person knowingly and willfull	to make to Rang departition of agency of the United

EnerVest Operating, LLC NMLC-031621-A: H.M. Britt #13 API: 30-025-06000 Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

H2S monitoring equipment to be on site.

- 1. **CHANGE:** Set CIBP@3430'. Cut & attempt to pull 5-1/2" csg @+/- 3300'.
- 2. **CHANGE:** Mix & pump a 25sx Class C neat plug from 3430'-3230'. WOC and Tag at 3230' or shallower (Covers 5-1/2" csg stub & 8-5/8" shoe plug)
- 3. Remove (covered in step 2)
- 4. Tag at 2405' or shallower Otherwise OK (Base of Salt plug)
- 5. Tag at 1055' or shallower Otherwise OK (Top of Salt plug)
- 6. WOC @ Tag at 567' or shallower Otherwise OK (13-3/8" shoe plug)
- 7. OK
- 8. OK
- 9. Submit a subsequent report to the BLM.

Ground level dry hole marker to be used for this well. Requirements attached.

, RGH 052010