



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

09-Jun-10

CELERO ENERGY II, LP

400 WEST ILLINOIS SUITE 1601

MIDLAND TX 79701-

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

ROCK QUEEN UNIT No.046

30-005-00878-00-00

Active Injection - (All Types)

L-26-13S-31E

Test Date: 5/27/2010

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 9/11/2010

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: OPERATOR CONCEDED BAD HAS PACKER LEAK; *****OPERATOR IN VIOLATION OF NMOCD
RULE 19.15.26.11 *****

ROCK QUEEN UNIT No.093

30-005-00934-00-00

Active Injection - (All Types)

N-36-13S-31E

Test Date: 5/27/2010

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 8/30/2010

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: OPERATOR CONCEDED BAD; HAS PACKER LEAK; *****OPERATOR IN VIOLATION OF NMOCD
RULE 19.15.26.11 *****

DRICKEY QUEEN SAND UNIT No.016**30-005-00973-00-00**

B-3-14S-31E

Active Injection - (All Types)
Test Date: 6/8/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 9/11/2010
Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: SURFACE CASING HAS A STRONG VACUUM; WILL BLEED OFF AND ONCE CLOSED AND
OPENED AGAIN COMMENCES TO SHOW A STRONG VACUUM AGAIN; ****OPERATOR IN
VIOALATION OF NMOCD RULE 19.15.26 11 ****

DRICKEY QUEEN SAND UNIT No.042**30-005-01076-00-00**

H-16-14S-31E

Active Injection - (All Types)
Test Date: 5/27/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 8/30/2010
Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: SURFACE CASING LEAK ****OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11 ****

WEST CAP QUEEN SAND UNIT No.004**30-005-01092-00-00**

H-17-14S-31E

Active Injection - (All Types)
Test Date: 6/8/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 9/11/2010
Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: CASING HAS SALT RESIDUE; CASING BUILDS BACK UP IMMEDIATELY; *****OPERATOR IN
VIOLATION OF NMOCD RUL 19 15.26.11 *****


In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,


Hobbs OCD District Office
COMPLIANCE OFFICER

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years, Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER 017H15554612
\$0.440
06/09/2010
Mailed From 88240

US POSTAGE

CELERO ENERGY II, LP
400 WEST ILLINOIS SUITE 1601
MIDLAND, TX 79701