Submit 1 Copy To Appropriate District Office	State of New Mo		Form C-103
<u>District I</u> Energy, Minerals and Natural Resources			October 13, 2009 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II CONSED_VATION DIVISION			30-025-28434
District III 1301 W. Grand Ave., Artesia, NM DISTRICT OF CONSERVATION DIVISION District III District III			5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe. NOBBSOLLIN			E-6002
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			B Lee State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 007
2. Name of Operator			9. OGRID Number
NADEL AND GUSSMAN PERMAIN LLC			155615
3. Address of Operator 601 N. MARIENFELD, STE 508			10. Pool name or Wildcat SCHARB, QUEEN
4. Well Location			
Unit Letter_H:	1980feet from theNO	RTH line and	660feet from theEASTline
Section 5	Township 19S	Range 35E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3894' GL			
Level the the transmission of the second sec	1 3094 GL		an admir a mana baka filmin, phi () 報告 () 報告 () an () () () () () () () () () (
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO:	CIID	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUB-			
			ILLING OPNS. □ PAND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or comp	leted operations. (Clearly state all	pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
03/23/10 Notify OCD 03/24/10 MIRU Mayo Marrs. ND WH, NU BOP. RIH w\ WL and tag cibp @ 4551'. POOH. PU tbg and TIH. Tag cibp circ well w\			
plugging mud. PU and spot 25 sxs @ 4064' TOH SDFN			
03/25/10 TIH and tag @ 3827'. PU and spot 25 sxs @ 3443'. TOH. RIH and perf @ 1907'. POH and press up to 700 psi. Call OCD.			
TIH and spot 30 sxs @ 1953'. TOH and woc. TIH and tag @ 1753'. Rih and perf @ 500'. POH. pump 35 sxs. SDFN 03/26/10 TIH and tag @ 301', toh. RIH and perf @ 60' pooh. Circ 20 sxs to surface. Dig out cellar and install PA marker. Clean up			
Location			
			ed for plugging of well bore only. ; under bond is retained pending receipt
		of C-103	(Subsequent Report of Well Plugging)
Spud Date:	Rig Release D	ate: which m	nay be found at OCD Web Page under

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Zem E, W	Clark TITLE N	M Operations Mgr.	DATE 06/01/2010
•			
Type or print name _K. E. McCready E-mail address: _kemm@naguss.com PHONE: _432-682-4429			
For State Use Only		4	
APPROVED BY	TITLE =	STAFF M	DATE 6-16-10
Conditions of Approval (if any):	,		