

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

RECEIVED
JUN 14 2010
HOBBS
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05457 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit ✓
8. Well Number 321 ✓
9. OGRID Number 157984 ✓
10. Pool name or Wildcat Hobbs; Grayburg-San Andres ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3698' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other PxA'd WIW
2. Name of Operator Occidental Permian Limited Partnership
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294
4. Well Location Unit Letter <u>G</u> : <u>2310</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>East</u> line Section <u>14</u> Township <u>18-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3698' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
forms, www.emnr.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 6/7/10

Mark Stephens@oxy.com

Type or print name Mark Stephens E-mail address: Mark Stephens@oxy.com PHONE (713) 366-5158

For State Use Only

APPROVED BY [Signature] TITLE Staff MGR DATE 6-16-10

Conditions of Approval (if any):

pm

North Hobbs G/SA Unit Well No. 321
API No. 30-025-05457

Plug and abandon the subject well as follows -

5/21/10 - 5/26/10:

MI x RU pulling unit. ND WH x NU BOP. TIH x tag cement at 419'. Drill out cement x CIBP from 419' - 472' x circulate clean. RIH x tag at 3870'. Circulate hole with 10# mud-laden fluid. Pull uphole to 3514' x spot 30 sx. Cl. 'C' cement. POOH x WOC 3.5 hrs. RBIH x tag at 3165'. Pull uphole to 2824' x spot 25 sx. Cl. 'C'. POOH x WOC overnight. RIH x tag at 2563'. Pull uphole x perf at 1700', 4 SPF. RIH x set packer at 1145'. Squeeze 30 sx. Cl. 'C' into perfs. Shut-in at 1000 psi x WOC 3 hrs. POOH with packer. RIH x tag at 1474'. Pull uphole to 589' x circulate 60 sx. Cl. 'C' to surface. POOH x top off. ND BOP. RD pulling unit x clean location.