Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
<u>District I</u> Energy, Minerals and Natural Resources			June 19, 2008 WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210 District III 1302 G. A. G. F.			30-025-28678
1000 Rio Brazos Rd. Aztec NM 87410 N 16 2010 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☒	
District IV 1220 S. St. Francis Dr., Santa Fe, NOBBSOCD Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name
PROPOSALS.)			Parks A 8. Well Number 12
Type of Well: Oil Well			9. OGRID Number 012024
John H. Hendrix Corporation			9. OGRID Nulliber 012024
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040			10. Pool name or Wildcat Blinebry Oil & Gas
4. Well Location			
Unit Letter I : 2310feet from theSouth line and330feet from theEast line			
Section 14 Township 22S Range 37E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3330' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			
DOWNHOLE COMMINGLE	_		
OTHER:	П	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion			
Propose to Downhole commingle Blinebry with existing Wantz Abo and Wantz Granite Wash perfs by removing plugs in place.			
1. MIRU. POOH w/ rods, pump. POOH w/ tbg. GIH and retrieve Baker Lokset BP @ 6500'. POOH			
 GIH and Drill out CIBP @ 7250'. POOH. GIH w/ pkr and set @ 6550'. Acidize existing W. Abo and W. Granite Wash perfs w/ 2500 gal 15% HCl. Swab test. 			
4. POOH. GIH w/ RBP and pkr and acidize Blinebry w/ 1500 gal 15% HCl. POOH.			
5. GIH w/ prod equipment. Test well.6. Return to production as DownHole Commingle: Blinebry, Wantz Abo and Wantz Granite Wash.			
o. Return to production as Do	win tole Commingle. Billieory, was	ntz Abo and wantz (oranite wash.
Spud Date:	Rig Release Da	.t	
Space Date.	- Rig Release Da	ite.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Courle Long Ham TITLE Engineer DATE 06/15/10			
SIGNATURE Courly Con	TITLE En	gineer	DATE 06/15/10
	oran Haynes . E-mail addres	ss: cdoranhaynes(a	<u>0jhhc.org</u> PHONE: 432-684-6631
For State Use Only		-	
APPROVED BY:	TITLE	INVESTMENT ENGIN	JUN 1 8 2010 DATE
Conditions of Approval (if any):			