District II 1301 W. Grand Ave., Artest RECEIVED CONSERVATION DIVISION 88210 District III 1000 Rio Brazos Rd., Aztec, NUL 0.8 2010 Santa Fe, NM 87505 87410 District IV			
1220 S. St. Francis Dr., Santa O, BBSOCD 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			
8. Well Number D-20			
2. Name of Operator LEGACY RESERVES OPERATING LP/ 9. OGRID Number 240974			
3. Address of Operator P.O. BOX 10848 MIDLAND, TX 79702 10. Pool name or Wildcat JUSTIS-BLINEBRY-TUBB-DRINKARE			
4. Well Location			
Unit Letter <u>H</u> : 2310 feet from the <u>NORTH</u> line and <u>330</u> feet from the <u>EAST</u> line. Section 23 Township T25S Range R37E NMPM LEA County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3032.4' GR			
Pit type Porth to Crown deuter Distance for the state of			
Pit typeDepth to GroundwaterDistance from nearest frsh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: OTHER: MAG M TREATMENT [X] 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: OTHER: MAG M TREATMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/10 - 2/17/10 MIRU pump truck and Baker Petrolite and 1 frac tank. Pump 300 bbls water mixed with 110 gal SRW-4804 Scale Removal Chemical and 10 gal RE-4574 Wetting Agent. Pump 20 bbls mix down tbg at 0.5 BPM and 200 bbls mix with 2 cylinders Mag M down tbg at 0.5 BPM. Flush 30 bbls mixture down tbg.			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: MAG M TREATMENT MAG M TREATMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/10 - 2/17/10 MIRU pump truck and Baker Petrolite and 1 frac tank. Pump 300 bbls water mixed with 110 gal SRW-4804 Scale Removal Chemical and 10 gal RE-4574 Wetting Agent. Pump 20 bbls mix down tbg at 0.5 BPM and 200 bbls mix with 2 cylinders Mag M down tbg at 0.5 BPM. Flush 30 bbls mixture down tbg. SI well overnight. Put back on ESP pumping.			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: MAG M TREATMENT ⊠ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/17/10 - 2/17/10 MIRU pump truck and Baker Petrolite and 1 frac tank. Pump 300 bbls water mixed with 110 gal SRW-4804 Scale Removal Chemical and 10 gal RE-4574 Wetting Agent. Pump 20 bbls mix down tbg at 0.5 BPM and 200 bbls mix with 2 cylinders Mag M down tbg at 0.5 BPM. Flush 30 bbls mixture down tbg. SI well overnight. Put back on ESP pumping. PERFS: 5046-5956' PBTD: 5980' TD: 5984'			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB Image: Comment of the second			

Conditions of A	pproval (if	any).
-----------------	-------------	-------