Submit 1 Copy To Appropriate District Office		State of New Mexico		Form C-103	
<u>District I</u> 1625 N French Dr , Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.		
District II 1301 W Grand Ave, Artesia CONSERVATION DIVISION District III 1220 South St. Francis Dr.			30-025-23765		
1220 Dutil Dt. 11ancis Dt.			5. Indicate Type of Lea	rse FEE 🛛 🖊	
1000 Rio Brazos Rd, Aztec, NM 87410 District IV IIII 1 3 2010 Santa Fe, NM 87505			6. State Oil & Gas Leas		
District IV 1220 S. St. Francis Dr., Santa Fe, Will 1 3 2010 Santa Fe, NM 87505					
SUNDRICO REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Hobbs G/SA Unit		
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other PXA'd WIW			8. Well Number		
			341		
2. Name of Operator Occidental Permian Limited Partnership			9. OGRID Number 157984 ✓		
3. Address of Operator			10. Pool name or Wildcat		
P.O. Box 4294, Houston, TX 77210-4294			Hobbs; Grayburg-San Andres		
4. Well Location				1	
Unit Letter O	:580feet from theSouth		feet from the	East line	
Section 18	Township 18-S 11. Elevation (Show whether DR,	Range 38-E	NMPM	County Lea 🗸	
3672' DF					
12. Check	Appropriate Box to Indicate N	ature of Notice, I	Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			C ALTE	RING CASING	
TEMPORARILY ABANDON			<u>=</u>	DA 🗆	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE					
DOWN TOLE COMMINTOLE					
OTHER:		OTHER: Location	is ready for OCD inspect	ion after P&A 🛛	
	n compliance with OCD rules and the	terms of the Operat	or's pit permit and closure	e plan.	
Rat hole and cellar have been filled and leveled Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the:					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANTENTLY STAMPED ON THE MARKER'S SURFACE.					
other production equipment.					
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 					
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.					
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not					
have to be removed.) All other environmental concerns have been addressed as per OCD rules.					
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed form					
non-retrieved flow lines and pipelines.					
When all work has been completed, return this form to the appropriate District office to schedule and inspection .					
SIGNATURE TOVON	M, ONG TITLE	HES Specialist	DATE_ <i>O</i>	7/09/2010	
Type or print name Steven M. Bishop E-mail address: Steven Bishop@oxy.com PHONE: (575) 397-8251					
For State Use Only					
APPROVED BY: Wash Whitzlen TITLE Compliance Officer DATE 07/15/2010					
APPROVED BY: Wark Whitzlen TITLE Coupling Officer DATE 0/115/2018 Conditions of Approval (if any):					

Zm