State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE RECEIVED CONSERVATION DIVISION	Revised 5-2/-2004
DISTRICT I 1220 South St. Francis Dr.	WELL API NO
1625 N. French Dr., Hobbs, NM 88240 DISTRICT II Santa Fe, NM 87505	30-025-05483 5 Indicate Type of Lease
	STATE X FEE
1301 W. Grand Ave, Artesia, NM 88210 OBBSOCD DISTRICT III	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	Section 24
1. Type of Well Oil Well X Gas Well Other	8. Well No. 231
Oil Well X Gas Well Other 2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
	et From The West Line
Unit Letter K: 1980 Feet From The South 2310 Fee	west Eme
Section 24 Township 18-S Range 37-I	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3669' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
Total division of the same samples and the same samples are samples and the samples are samples and the samples are samples and the samples are sample	
Situation of the situat	Acid Fledt
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. RU wireline and perforate tubing @3753'. NU BOP/ND wellhead. 	
 POOH w/tubing & ESP equipment. RIH w/bit. NU power swivel & stripper head. Tag CIBP @4225'. Drill out bridge plug. Clean out to new PBTD of 4361'. RD power swivel & 	
stripper head. POOH w/bit.	out to new 1 b 1 b of 4301. Rb power swiver &
5. RIH w/straddle acid packer. RU HES & acid treat well w/1680 gal of 15% PAD acid in 5 settings	s. 50 bbl fresh water flush. RD HES.
6. Perform scale squeeze w/100 gal of EC6490 mixed with 100 bbl of fresh water and flush w/200 b	obl of fresh water. POOH w/packer.
7. RIH w/ESP equipment set on 119 jts of 2-3/8" tubing. Intake set @3788'. 8. ND BOP/NU wellhead.	
9. RDPU & RU. Clean location & return well to production.	
RUPU 05/07/2010 RDPU 05/13/2010	0
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be	
constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved	
SIGNATURE Mencly Cohoon of the Administrative Associate DATE 07/14/2010	
TYPE OR PRINT NAME Mendy Adjointson E-mail address: mendy johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only	
APPROVED BY TITLE STAFF	MAR DATE 7-19-10
CONDITIONS OF APPROVAL IF ANY	