Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103
District I	Energy, Minerals and Natural Resources			WELL ADINO	May 27, 2004
1625 N. French Dr., Hobbs. NM 88240 District II				WELL API NO.	25-33114
District II 1301 W Grand Ave., Artesia RECEVEDIL CONSERVATION DIVISION				5. Indicate Type of	Lease
District III 1220 South St. Francis Dr.			STATE 🛛	FEE 🗌	
1000 Rio Brazos Rd, Aztec, NM 87410 1 9 2010 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas	Lease No. 1258-1
SUNDA OFFICES AND REPORTS ON WELLS					Init Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				New Mexico AE St	
	Gas Well Other	r 🗸	/	8. Well No. 27	
2. Name of Operator /				9. OGRID Number	40974
Legacy Reserves Operating LP 3. Address of Operator				10. Pool name or W	
PO Box 10848, Midland, TX 79702					n, Blineberry
4. Well Location				ć	
Unit Letter F: 2170 feet from the North line and 1650 feet from the West line					
Section 12 Township T-18-S Range R-34-E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
The same of the sa	11. Lie vation (5/10%	GL: 3996	KB: 4011		
Pit or Below-grade Tank Applic	cation or Closure			2000-0000000000000000000000000000000000	
Pit type Depth to Grou	Auto-re-territory			Distance from neare	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUE					ORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK				<	ALTERING CASING 🔲
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A					
PULL OR ALTER CASING [MULTIPLE COMPLETION		CASING/CEMENT	JOB \square	
્રક્					
OTHER:		<u> </u>	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or					
recompletion.					
06/29/10 MIRU rig and cementing equipment. ND well head, NU BOP. Pick up workstring. RIH and tag plug @ 7150'. circulate hole w/ mud laden fluid. Spot 10 sx cement on top of plug. POH to 6600'. SDFN.					
06/30/10 Spot 25 sx cement @ 6600'. POH to 4850'. Spot 25 sx cement plug. POH to 3300'. Spot 50 sx cement plug. POH to					
1730'. Spot 25 sx cement plug. Pull out of cement. WOC. Tag plug @ 1578'. POH to 400'. Circulate 50 sx cement to surface. Lay					
down tbg. and ND BOP. rig down clean location move off. 07/06/10 Move in Welder and backhoe. Dig out cellar, cut off wellhead, Weld on Dry Hole Marker. Back fill cellar, cut of dead					
men. and clean location, move off.					
r					V
	Apı	proved for pluggi	ng of well bore only.		
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)					
projection of the second of th	whi	ich may be found	l at OCD Web Page unde	rt .	
	For	m*, www.cmntd.	atato.nm.us/oca:		
*3.5					
Ishereby certify that the information	above is true and complete	to the best of n	ny knowledge and bel	ief. I further certify that	t any pit or below-grade tank
has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.					
SIGNATURE DANS	Johnson	- TITL E F	Production Sup	erintendent	DATE 07/15/10
	~) ·				
Type or print name Berry J	olmson	E-mail addr	ess:	Telepho	one No.432-689-5200
For State Use Only		,	_		
APPROVED BY		TITLE	STAR D	BZ	DATE 7-19-10
Conditions of Approval (if any):	18				
	//		Form provided by	y Forms On-A-Disk · (214)	340-9429 · FormsOnADisk.com