Submit 3 Copies To Appropriate District	State of New Me			Form C-103
Office District 1	Energy, Minerals and Natu	iral Resources		May 27, 2004
1625 N. French Dr., Hobbs 13M287240			WELL API NO.	0745
1625 N. French Dr., Hobbs 13, 197240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.			30-041-2 5. Indicate Type of 1	
			1	
1000 Rio Brazos Rd., Aztec, NM \$1/410 9 2	UIU Santa Fe, NM 8	37505	STATE	FEE 🗴
1220 S. St. Francis Dr., Santa PONBISO	CD		6. State Oil & Gas L	ease No.
SUNDRY NOTIC	ES AND REPORTS ON WE	LLS	7. Lease Name or Ut	nit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			WILCOX TS	
1. Type of Well: Oil Well X Gas Well Other			8. Well Number	/
2. Name of Operator			9. OGRID Number	100.
ENERVEST OPERATING L.L.C.	ATIN: BRIDGET HE	LFRICH	195	3197
3. Address of Operator			10. Pool name or W	
1001 FANNIN ST., STE. 800, 4. Well Location	HOUSTON, TEXAS 77002		TOMAHAWK (SAN AN	DRES)
4. Well Location				
Unit Letter H:	1650 feet from the NO	RTH line and	990 feet from	the EAST line
Section 19	Township 078		NMPM	County ROOSEVELT
	11. Elevation (Show whether 4,46		tc.)	
Pit or Below-grade Tank Application				
Pit type STEEL Depth to Groundwater.				
Pit Liner Thickness: mil	Below-Grade Tank: Volume.	bbls; Constructi	on Material * NONE WI	THIN 1,000'.
12 Charle A	mmanniata Day ta Indiaata	Notine of Notice	Domant on Other I	Data
	ppropriate Box to Indicate	·	• '	
		SEQUENT REPO		
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS. 🔲	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		, is in bonnier.
OTHER:		OTHER:		
13. Describe proposed or completed	operations (Clearly state all po	ertinent details, and give	ve nertinent dates, incl	uding estimated date
of starting any proposed work). or recompletion.			-	•
1) POOH W/ RODS X TUBING.				
2) SET 4-1/2" CIBP @ 4,000	': PIMP A 25 SX. OMT PIII	IG @ 4.000!-3.750!	CTRC WELL W/ PXX	MID
3) PUMP A 25 SX. CMT. PLUG		•	CIIC. WILL NY 132	Tab.
4) PERF. X ATTEMPT TO SQZ.	•		X B/SALT): WOC X	TAG OMT. PLUG.
5) CUT X PULL 4-1/2" CSG.				
	X TAG TOP OF CMT. PLUG.			
6) MIX X CIRCULATE TO SURE	ACE A 50 SX. OMT. PLUG @	150'-3'.		
7) DIG OUT X OUT OFF WELLH	EAD 3' B.G.L.; WELD ON ST	EEL PLATE TO CASIN	IGS X INSTALL DRY H	IOLE MARKER.
I hereby certify that the information a	bove is true and complete to the	e best of my knowled	ge and belief I further	certify that any nit or helow-
grade tank has been will be constructed or o				
SIGNATURE Jan	A. Z. TIT			ATE 07/15/10
SIGNATURE	1		DEYLER@MILAGRO-RES	1112
Type or print name DAVID A. EYLER		nan addiess.		one No. (432) 687–3033
For State Use Only		_		
APPROVED BY	/ //	C_{-n}	2.200	
Conditions of Approval, if any:	my min	11 E 2744	MAR TA	TE 7-20-10
	TIT			TE 7-20-10
	TI		prvation Division Must or to the beginning of p	be notified

PLUGGING & ABANDONIMENT WORKSHEET (2STRING CSNG) **OPERATOR** ENERVEST OPERATING LLC 30-041-26745 LEAȘENAME WILCOX Dic 1984 ULH WELL # 004 075 RNG SECT 32E 990 ENL **FROM** FORMATION @ TD 4.350' TD: FORMATION @ PBTD PBTD: SIZE SET @ TOC TOC DETERMINED BY 8-5/8 SURFACE 1.665' SURF. CIRC. INTMED 1 INTMED 2 4-1/2" 2,750 CALC . 4.350' PROD SIZE TOP BOT TOC DETERMINED BY LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 4,026 - 4,269 **PERFS** INTMED 2 OPENHOLE PROD * REQUIRED PLUGS DISTRICT I PLUG **TYPE** SACKS DEPTH RUSTLER (ANHYD) PLUG **CMNT** YATES EXAMPLES QUEEN 2-3/3"c+-4,000" 25 SXS PLUG#1 OH9850' GRAYBURG SHOE 50 SXS 8700'-8800' PLUG#2 SAN ANDRES CIBP/35' 5300 PLUG#3 5300' PLUG#3 CIBP 25 SXS CAPITAN REEF PLUG#4 STUB 50 SXS 4600'-4700' 200 SXS 400 RETNR SQZ PLUG#6 DELAWARE 0-10' **SURF** 10 SXS PLUG#7 BELL CANYON PLUG#1 CHERRY CANYON PLUG#2 BRUSHY CANYON PLUG#3 BONE SPRING PLUG#4 PLUG#5 GLORIETA BLINEBRY PLUG#6 PLUG#7 DRINKARD PLUG#8 PLUG#9 ABO PLUG# 10 PLUG# WC PLUG# PENN STRAWN ATOKA MORROW TD 4,350 DEVONIAN