Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 June 19, 2008
District 1 Energy, Minerals and Natural Resources 1625 N French Dr , Hobbs, NM88240		WELL API NO.	
District II OTL CONSERVATION DIVISION			30-005-29021
1301 W Grand Ave, Artesia, NM 88210 District III 1220 South St. Francis Dr			5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87406 U 2 ZUIU Sonta Fe NIM 87505			STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr , Santa Fe, NOBBSOCD 87505			6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CATO SAN ANDRES UNIT
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other Injector			8. Well Number CSAU 50
2. Name of Operator CANO PETRO OF NEW MEXICO, INC.			9. OGRID Number 248802
3. Address of Operator			10. Pool name or Wildcat
801 Cherry St. Unit 25 Suite 3200, Fort Worth, TX 76102		Cato; San Andres	
4. Well Location Unit Letter, J 1980 feet from the South line and 1922 feet from the East line and 1922.			
Offit Letter lett from the line and lett from the line			
Section 11 Township 8S Range 30E NMPM County Chaves 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4149 GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON			
DOWNHOLE COMMINGLE			
- Contains lead			
OTHER: fix tubing leak 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. work performed 6/1/2010 - 6/4/2010 current perfs 3496-3540', 3564-3590', 3644-3678'			
			MIRU pulling unit
Unset packer and POOH w/ 2-3/8" lined tubing and packer			
Found hole in tubing on 4th joint from bottom			
Replaced that joint and RBIH w/ 2-3/8" lined tubing and packer. Set packer @ 3400'			
Loaded backside with fresh water and packer fluid			
Performed mechanical integrity test, and it passed (documentation enclosed)			
	Resumed water injection		
Spud Date: 03/24/08	Rig Release Da	te: 04/08/08	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Collidan	TITLE Engi	neer	DATE 7/29/2010
Type or print name Collin Strawn E-mail address: PHONE: 817-698-0900			
For State Use Only			
APPROVED BY: DATE 8-4-10 Conditions of Approval (if any): DATE 8-4-10			
Conditions of Approval (if any):			
			B. 4 # 114

