Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

_	Lease Serial No.
J.	Lease Seliai Ino.
	NMI C031621A

SUNDRY NOTICES AND REPORTS ON WELLS AUG 12 2010 Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals BBSOCD

6. If Indian, Allottee or Tribe Name

	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		" PTTODD,	3000			
SUBMIT IN TRI	7. If Unit or CA/A	Agreement, Name and/or No					
1. Type of Well						No.	
Oil Well 🔀 Gas Well 🗖 Ot	BRITT 14						
Name of Operator ENERVEST OPERATING LL	9. API Well No. 30-025-3515	52-00-S1 /					
3a. Address 1001 FANNIN ST., SUITE 80 HOUSTON, TX 77002-6708	o. (include area code 95-6537 5-1429	e)	10. Field and Pool EUMONT	l, or Exploratory			
4. Location of Well (Footage, Sec., 7	J-1429	···	11. County or Par	ish and State			
Sec 7 T20S R37E NWSE 1400FSL 2310FEL						LEA COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	) INDICATI	E NATURE OF	NOTICE, RE	EPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
- Nation of Intent	Acidize	□ Dee	Deepen Pro		uction (Start/Resume) Water Shut-		
□ Notice of Intent	Alter Casing	_	ture Treat Reclamation			Well Integrity	
Subsequent Report Subsequent Re	Subsequent Report		v Construction	Recomplete		Other	
☐ Final Abandonment Notice	Change Plans	_	g and Abandon	<b>-</b>			
	Convert to Injection		g Back	☐ Water D			
Attempt to locate csg leak and 6-14-10: MIRU PU. Un-hang fish, unseat pump. POOH w/r of 106 jts 2-3/8" tbg. RD scan 6-15-10: TIH w/7" straddle as Held good. PUH w/packer, at packer & close BOP. Press te release RBP. POOH w/tbg &	well. Rods parted. POO 139 x 3/4" rods & pump. Noners. SWI, SDON. sembly. Set RBP @ 2974 tempt to locate csg leak.	H w/30 x 3/4 ND WH. NU 4' w/packer ( Csg held 50	" rods. RIH w/fis BOP. RU tbg so 20 2917'. Press to 0 psi each settin	test SA to 10	OH w/total $\mathbb{R}^{[0]}$	ECEIVED UG 12 2010	
6-16-10: RIH w/6-1/8" bit w/cs	s 3079'-3342').  F	POOH w/tbg.	HC	DBBSOCD			
14. Thereby certify that the foregoing is	Electronic Submission #8	ST OPERATIN	G LLC. sent to the	ne Hobbs			
Name (Printed/Typed) BRIDGET	HELFRICH		Title REGUL	ATORY TEC	H.		
Signature (Electronic S	Date 07/13/2	010					
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E		
Approved By ACCEPT	DUSTIN W TitlePETROLE		ER .	Date 08/10/2			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	Office Hobbs		FETA	OLEUM ENGINEER 1 3 2010			

## Additional data for EC transaction #89472 that would not fit on the form

## 32. Additional remarks, continued

LD BHA. RIH w/7" SA. Set RBP @ 2974'. PUH 1 jt w/PSA 2943'. Press test tools to 500 psi. OK. PUH w/pkr & reset @ 1483'. Press dwn tbg to 500 psi w/no bleed off. Release pkr, close BOP & press csg from surf to RBP to 500 psi w/no bleed off. Release pkr & retrieve RBP. POOH LD RBP. RIH w/10 jts tbg & pkr. Set pkr @ 3048' w/ end of tbg @ 3360'. SWI, SDON.

6-17-10: RU swab. Made 1st swab run, no fluid. Made 3 more runs every 2 hrs. Hole dry. RD swab. SWI, SDON.

6-18-10: SITP - 0 psi. SICP - 0 psi. Made 1 swab run - no fluid. RD swab. Release pkr & PUH w/ end of tbg @ 3125'. RU pump truck & spot 400 gals 15% HCL acid across perfs. Flush w/ 14 bbls 2% KCL. POOH w/ tbg & pkr. RIH w/MA - SN on 106 jts 2-3/8" tbg. Space out & hang on unit. Press test tbg & pump to 500 psi. OK. Good pump action. RD truck.

6-19-10: Unhang well. Add 4' rod sub. Re-space well. RU pump truck & press up tbg to 500 psi. Held good. No pump action. Long stroke pump w/pulling unit. Pump started stroking to 500 psi. RDMO truck and pulling unit. Well returned to production.