Submit 3 Copies Office	To Appropriate District	State of New M		7	6-025-1119	11 / Form C-103	
		Energy, Minerals and Na	tural Resou	irces	LL API NO.	June 19, 2008	
District I 1625 N. French Dr., Hobbs, NM88210 District II 1301 W Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.					30-0	2525682	
1301 W Grand Ave., Artesia, NM 88210 TONSER VATION DIVISION  District III 1220 South St. Francis Dr.					ndicate Type of I	Lease	
1000 Rio Brazos Rd., Aztec, NM 846 27 2010 Sonto Fe NIM 87505					STATE	FEE □ Fed 🖾	
District IV 1220 S. St. Francis Dr., Santa F OBBSOCD 87505					State Oil & Gas L NM 12612	ease No.	
87505			~				
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  PROPOSALS)  1. Type of Well: Oil Well  Gas Well  Other Injector					Lease Name or Un NM 70962X Well Number 1	nit Agreement Name Cooper Jal Unit	
2. Name of Operator					OGRID Number	198003	
Resaca Operating Company					10. Real name on Wildoot Jalmot: Tana		
3. Address of Operator 2600 W. I-20, Odessa, TX 79763					10. Pool name or Wildcat Jalmat; Tans, Yates, 7R/LM; 7R, Q		
4. Well Loca	- / //\						
Unit Letter :660feet from theSouth line and660feet from theWestline							
Secti		Township 24S	<del></del>	37E	NMPM Lea	County \	
		Elevation (Show whether D 3,326' G		GR, etc.)			
<u> </u>	The second secon						
	12. Check Appr	opriate Box to Indicate	Nature of 1	Notice, Repo	ort or Other Da	nta	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK						TERING CASING	
TEMPORARILY ABANDON						AND A	
PULL OR ALT	「ER CASING ☐ MU COMMINGLE ☐	JLTIPLE COMPL	CASING	CEMENT JOE	3 Ц		
DOWNIOLL	COMMINGEL						
	rform Step-Rate Test.		OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
or recompletion.  Objective: Perform Step-Rate Test							
		•	i			ng only Cannot increase a Fe office has approved	
•	vell in 24 hours prior to te	st.		•		on for Injection pressure	
	Arc Pressure Data, Inc. with pressure bomb and loc	eate at mid-nerfs	1	ıncrease		, .	
4) Start injection at 100 bwpd for 1 hour.							
5) Ramp rates up at 100 – 200 bwpd increments per hour.							
		parting pressure and 3 – 4 po	oints after pa	rting pressure.			
Note: Maximum rate should be 1500 bwpd.  6) POOH with pressure bomb. R. D. Arc Pressure Data, Inc.							
	well on injection at 400 by						
Γ	2/14/50			0/21/0	2010	1	
Spud Date:	2/14/50	Rig Release	Date:	8/31/2	2010		
_		<del></del>	<u> </u>			1	
I hereby certify	that the information abov	e is true and complete to the	best of my k	nowledge and	belief.		
	4 -		•	-			
SIGNATURE_	Bonus Cary	TITLE	_District En	igineer	DATE	8/2 <u>6</u> /2010	
						<u> </u>	
Type or print no <b>For State Use</b>		rrizates E-mail addr	ess: Doming	go. <u>Carrizales@</u>	tear.com PHC	ONE: <u>(432)580-8500</u>	
						02.	
APPROVED B Conditions of A	Approval (if any).	TITLE =	27744	MGZ	DATE	8-30-10	

