Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

. OCD Hobbs

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

5 Lease Serial No. LC-030174-B

6 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE – Other instructions on page 2.			7 If Un	7 If Unit of CA/Agreement, Name and/or No.	
1. Type of Well		-			
Oil Well Gas W	Vell ✓ Other In	jection 🗸	W.H. F	Name and No. thodes B Fed	eral NCT 1 #19
2 Name of Operator B C Operating, Inc.			9. API V 30-025	Well No. -25426	/
3a Address P O Box 50820 Midland, TX 79710	,	3b. Phone No. (include area c 432-684-9696 ext 253	· ·	d and Pool or E s Yates; Seve	en Rivers
4 Location of Well (Footage, Sec , T., F -330 FNL & 1980 FEL, Unit Letter J Section 26, T26S-R37E	R., M., of Survey Description	i)		ntry or Parish, punty, NM	State
12 CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	RE OF NOTICE, REPO	ORT OR OTHE	ER DATA
TYPE OF SUBMISSION		T	YPE OF ACTION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (St	art/Resume)	Water Shut-Off Well Integrity
✓ Subsequent Report	Casing Repair	New Construction	Recomplete		Other Return to
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily A Water Disposa		injection.
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final Adetermined that the site is ready for	peration: Clearly state all pe lly or recomplete horizonta ork will be performed or pr ed operations. If the operat Abandonment Notices must	rtinent details, including estimat lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple completi	ed starting date of any d measured and true ve BLM/BIA. Required son or recompletion in	proposed work rtical depths of subsequent repo a new interval,	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed onc
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring.	peration: Clearly state all peration: Clearly state all perally or recomplete horizontal fork will be performed or pred operations. If the operate Abandonment Notices must final inspection.)	rtinent details, including estimat illy, give subsurface locations and ovide the Bond No. on file with ion results in a multiple completing be filed only after all requirement	ed starting date of any d measured and true ve BLM/BIA. Required son or recompletion in	proposed work rtical depths of subsequent repo a new interval, ion, have been	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed one completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz	peration: Clearly state all peration: Clearly state all perality or recomplete horizontal fork will be performed or pred operations. If the operate Abandonment Notices must final inspection.) The perfect of the perf	rtinent details, including estimat illy, give subsurface locations and ovide the Bond No. on file with ion results in a multiple completing be filed only after all requirement	ed starting date of any d measured and true ve BLM/BIA. Required son or recompletion in	proposed work rtical depths of subsequent repo a new interval, ion, have been	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed one completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handle of the complete horizontal inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Son effective 8/17/10	rtinent details, including estimat lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple complete be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any d measured and true ve BLM/BIA. Required s on or recompletion in its, including reclamat	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed one completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and 6. Pressure test to 300 psi, hold for 3.	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handle of the complete horizontal inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Son effective 8/17/10	rtinent details, including estimat lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple complete be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any d measured and true ve BLM/BIA. Required s on or recompletion in its, including reclamat	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed one completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and 6. Pressure test to 300 psi, hold for 3.	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handle of the complete horizontal inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Son effective 8/17/10	rtinent details, including estimat lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple complete be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any d measured and true ve BLM/BIA. Required s on or recompletion in its, including reclamat	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed one completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and 6. Pressure test to 300 psi, hold for 3.	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handle of the complete horizontal inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Son effective 8/17/10	rtinent details, including estimat lly, give subsurface locations and ovide the Bond No. on file with ion results in a multiple complete be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any d measured and true ve BLM/BIA. Required s on or recompletion in its, including reclamat	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and 6. Pressure test to 300 psi, hold for 3.	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handonment Notices must final inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Joins, chart is attached. Mins, chart is attached.	rtinent details, including estimat lly, give subsurface locations ani ovide the Bond No. on file with ion results in a multiple completi be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any d measured and true ve BLM/BIA. Required s on or recompletion in its, including reclamat	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has
13. Describe Proposed or Completed Op the proposal is to deepen directiona Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for 1. RIH pull and LD tubing. 2. Clean out to 3235'. 3. RIH w/ packer set @ 3100', acidiz 4. POH LD packer and workstring. 5. RIH w/ 2-3/8" injection tubing and 6. Pressure test to 300 psi, hold for 3. This well has been returned to injecti Pressured casing to 550 psi for 30 m.	peration: Clearly state all peully or recomplete horizonta fork will be performed or pred operations. If the operation handonment Notices must final inspection.) The perfective 3146-3215' w/ 30 packer, set @ 3085'. 30 min, held ok. Joins, chart is attached. Mins, chart is attached.	rtinent details, including estimat lly, give subsurface locations ani ovide the Bond No. on file with ion results in a multiple completi be filed only after all requirement 000 gals 15% NEFE acid.	ed starting date of any dimeasured and true versible. Required son or recompletion in a starting reclamation of the starting reclamation of th	proposed work ritical depths of subsequent repe a new interval, ion, have been AUG	f all pertinent markers and zones. orts must be filed within 30 days a Form 3160-4 must be filed once completed and the operator has

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or person of the West Fy W. INGRAM.

(Instructions on page 2)

entitle the applicant to conduct operations thereon

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Approved by

