State of New Mexico Energy, Minerals and Natural Resources Department

Energy, Minerals and Natural Resources Department	nt Form C-103
FILE IN TRIPLICATE DISTRICT 1 1220 South St. Francis Dr.	nt Form C-103 Revised 5-27-2004
1625 N French Dr., Hobbs, NM, 88240	WELL API NO. 30-02527435
DISTRICT II SEP 0 1 2010	5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III HOBBOOT	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	North Hobbs (G/SA) Unit Section 19
1 Type of Well.	8 Well No 943
Oil Well X Gas Well Other 2 Name of Operator	9 OGRID No 157984
Occidental Permian Ltd.	3 OGRID NO 137984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4 Well Location	
Unit Letter H 2470 Feet From The North 225 Fee	et From The East Line
Section 19 Township 18-S Range 38-F	E NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3655'	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	<u> </u>
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	IT JOB
OTHER: Clean out/Acid treat X OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
	,
1. Kill well. POOH w/ESP & equipment.	
 RIH w/bit and clean out to PBTD @4407'. Acid treat well w/1596 gal of 15% PAD acid. 	
4. Perform scale squeeze.	
5. Run back in hole w/ESP equipment.	
6. Return well to production.	
	(
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	that any nit or below grade tank has been/will be
constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative	e OCD-approved
SIGNATURE Mendy Ci Cohmon TITLE Administrative Associate DATE 08/30/2010	
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_johnson@oxy.com	TELEPHONE NO 806-592-6280
For State Use Only APPROVED BY SEP 0 2 2010	
APPROVED BY TITLE PETROLE	DATE SEP U Z ZUIU