## RECEIVED

Submit 3 Copies To Appropriate Distage 1 3 2010 State of New Mex Office	Form C-103
Submit 3 Copies To Appropriate District I  1625 N French Dr., Hobbs, NM 88240BBS  OIL CONSERVATION	ral Resources March 4, 2004 WELL API NO.
District II  130 W. Grand Avg. Artesia, NM 88210  OIL CONSERVATION	DIVISION 30-025-05408
District III 1220 South St. Fran	5 Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 District IV Santa Fe, NM 87	SIAIL LI ILL LI
1220 S St Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FO	G BACK TO A R SUCH Lovington San Andres Unit (26748)
PROPOSALS)	8. Well Number ,
1. Type of Well: Oil Well  Gas Well  Other	37
2. Name of Operator	9. OGRID Number
Chevron Midcontinent, L.P.	241333
3. Address of Operator #15 Smith Rd., Midland, Tx 79705	10. Pool name or Wildcat  Lovington; Grayburg -SanAndres (4058)
4. Well Location	Lovington, Orayoung Carwinance (1995)
	line and 990 feet from the East line
Unit Letter A : 330 feet from the North	line and 990 feet from the East line
	nge 37-E NMPM Lea County
11. Elevation (Show whether DR,	RKB, RT, GR, etc)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form	
Pit Location: UL A Sect 6 Twp 17S Rng 37E Pit type Steel De	pth to GroundwaterDistance from nearest fresh water well_Over 100
Distance from nearest surface water Below-grade Tank Location UL	SectTwp;
Distance from nearest surface water	
	the second secon
	•
12. Check Appropriate Box to Indicate N	ature of Notice, Report or Other Data
NOTICE OF INTENTION TO:	ature of Notice, Report or Other Data SUBSEQUENT REPORT OF
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	ature of Notice, Report or Other Data  SUBSEQUENT REPORT OF:  REMEDIAL WORK   ALTERING CASING
NOTICE OF INTENTION TO:	ature of Notice, Report or Other Data  SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   TEMPORARILY ABANDON   CHANGE PLANS	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER.	CASING TEST AND CEMENT JOB  AUTOR OF Notice, Report or Other Data  SUBSEQUENT REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  Detertinent details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER	CASING TEST AND CEMENT JOB  AUTOR OF Notice, Report or Other Data  SUBSEQUENT REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER.   13. Describe proposed or completed operations. (Clearly state all pof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  Detertinent details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER.   13. Describe proposed or completed operations. (Clearly state all prof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 Spiace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL	SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  Detrinent details, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of proposed completion  O Install Dry Hole Marker & Clean Location
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  TEMPORARILY ABANDON  CHANGE PLANS  PULL OR ALTER CASING  MULTIPLE COMPLETION  OTHER.   13. Describe proposed or completed operations. (Clearly state all prof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs pnor to MIRU to P & A equipment 7 9/8/1 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10  3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10	SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  Dertinent details, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of proposed completion  Approved for plugging of well bore only.  Liability under bond is retailed pending receipt.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profits of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Noxified OCD 24 hrs pror to MIRU to P & A equipment 7 9/8/12 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10 5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@1760' 9/7/10	SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  Dertinent details, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of proposed completion  Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profits of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs pror to MiRU to P & A equipment 7 9/8/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3475' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10 5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@Surf 9/7/10 6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10	SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER Certinent details, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of proposed completion  Install Dry Hole Marker & Clean Location  Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.counted state by terrory.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profits of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Noxified OCD 24 hrs pror to MIRU to P & A equipment 7 9/8/12 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10 5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@1760' 9/7/10	SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER CASING TEST AND CEMENT BETT AND CEMENT BETT AND CEMENT SOBOLOGY  DINITIAL DRIVE BY THE COMMENT CASING TEST AND CEMENT SOBOLOGY  OTHER CASING TEST AND CEMENT SOBOLOGY  OTHER CASING TEST AND CEMENT SOBOLOGY  DINITIAL DRIVE SOBOLOGY  Approved for plugging of well bore only.  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cnurd.state.htm.to/ced.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all professor or recompletion.)  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 29/2/10 Unable to get Down W/CIBP, Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10  3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 49/3/10 Perf@2437' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt)  WOC Tagged@3125' 97/10  5 9/7/10 Perf@240' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe)  WOC Tagged@1760' 97/10  6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE. COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profisarting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 7 9/8/10 Unable to get Down w/CIBP, Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10  3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@2140' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10  5 9/7/10 Perf@2140' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE  TITLE	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profits of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs pror to MIRU to P & A equipment 79/8/12 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3375' Unable to EPIR Spot 35sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10 5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@3125' 9/7/10 6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10 I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE  TITLE METALLY TITLE ME	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE. COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profisarting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 79/81/10 Unable to get Down wCIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10  3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 49/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10  5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@1760' 9/7/10  6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE  Type or print name  Timmy BAGLEM  E-mail ad	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all profits of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs pror to MIRU to P & A equipment 79/8/12 2 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC Tagged@4233' 9/3/10 3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 4 9/3/10 Perf@3375' Unable to EPIR Spot 35sx C Cmt@3425' (B Salt) WOC Tagged@3125' 9/7/10 5 9/7/10 Perf@2140' Unable to EPIR Spot 35sx C Cmt@2190' (T Salt/Shoe) WOC Tagged@3125' 9/7/10 6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10 I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE  TITLE METALLY TITLE ME	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all prof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 79/8/12 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt@4600' WOC 74gged@4233' 9/3/10  3 9/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 49/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt@3425' (B Salt) WOC 74gged@3125' 9/7/10  5 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  6 9/7/10 Perf@400' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  I hereby certify that the information above is true and complete to the begrade tank has been/will be onstructed or closed according to NMOCD guidelines SIGNATURE  Type or print name  Timmy BAGLEY  E-mail ad  (This space for State use)	SUBSEQUENT REPORT OF:  REMEDIAL WORK
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER.  13. Describe proposed or completed operations. (Clearly state all prof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1 8/31/10 Notified OCD 24 hrs prior to MIRU to P & A equipment 79/8/12 9/2/10 Unable to get Down w/CIBP. Spot 30sx C Cmt(@4600' WOC 13gged@4233' 9/3/10 39/3/10 Displace Hole w/MLF, 9 5# Brine w/12 5# Gel P/BBL 49/3/10 Perf@3375' Unable to EPIR Spot 30sx C Cmt(@4600' WOC 13gged@3125' 9/7/10 59/7/10 Perf@240' Unable to EPIR Spot 30sx C Cmt(@2190' (T Sall/Shoe) WOC 13gged@1760' 9/7/10 6 9/7/10 Perf@240' SQZ&Circ 125sx C Cmt to Surf (Fr Wtr/Surf) WOC Tagged@Surf 9/7/10  I hereby certify that the information above is true and complete to the begrade tank has been/will be onstructed or closed according to NMOCD guidelines SIGNATURE  Type or print name Timmy BAGLEY E-mail ad (This space for State use)	SUBSEQUENT REPORT OF:  REMEDIAL WORK