District I	State of New Mex Energy, Minerals and Natura		Form C-103 May 27, 2004
		1	WELL API NO. 30-025-11759
1301 W. Grand Ave., Artesia, NM	1220 South St. Fronce	IVISION	5. Indicate Type of Lease
District III	1220 South St. France	CIS Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM	SEP 15 2010 Santa Fe, NM 875	005	6. State Oil & Gas Lease No.
87410 District IV	-ngsOCV		•
87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, N 87505	MORPA		
87505			
(DO NOT USE THIS FORM FOR PF	TICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PI PPLICATION FOR PERMIT" (FORM C-101) FO		7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT
1. Type of Well: Oil Well	Gas Well Other	,	8. Well Number F-24
2. Name of Operator LE	GACY RESERVES OPERATING LP		9. OGRID Number 240974
3. Address of Operator P.6	O. BOX 10848		10. Pool name or Wildcat
	DLAND, TX 79702		JUSTIS-BLINEBRY-TUBB-DRINKARD
4. Well Location			
	980 feet from the NORTH	line and	1980 feet from the WEST line.
Section 25	Township T25S Rang		NMPM LEA County
F A SAME AND A SAME	11. Elevation (Show whether DR		
	3058' GL 3070' KB	, , , , , , , , , , , , , , , , , , , ,	
Pit or Below-grade Tank Applicatio			(2000-2017-2013) Selection (1990-2013) Selection (1997-2013) Selec
Pit typeDepth to Gre	oundwaterDistance from nearest frs	h water well	Distance from nearest surface
water			
Pit Liner Thickness:	mil Below-Grade Tank: Volume	hi	ols; Construction Material
The Line of the Control of the Contr			os, Constituction material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
		01.10.0	·
NOTICE OF			
NOTICE OF			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK [☐ PLUG AND ABANDON ☐ R	EMEDIAL WORK	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C	EMEDIAL WORK	ALTERING CASING LING OPNS. P AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C	EMEDIAL WORK	ALTERING CASING LING OPNS. P AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT	ALTERING CASING LING OPNS. P AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER:	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C ☐ RTP & SPOT ACID ☑ C	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT	☐ ALTERING CASING ☐ LING OPNS.☐ P AND A ☐ JOB ☐
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C ☐ RTP & SPOT ACID ☑ C	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det	ALTERING CASING LING OPNS. P AND A DOB A ails, and give pertinent dates, including
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C RTP & SPOT ACID C completed operations. (Clearly state ing any proposed work). SEE RULE ompletion or recompletion.	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det	ALTERING CASING LING OPNS. P AND A DOB A ails, and give pertinent dates, including
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON R CHANGE PLANS COMPL COMPLETE AND COMP	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab ti	ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING DAME DE LING OPNS. PAND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON R CHANGE PLANS COMPL COMPLETE AND COMP	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab ti	ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING DAME DE LING OPNS. PAND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON R CHANGE PLANS COMPL COMPLETE AND COMP	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab ti	ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING LING OPNS. PAND A DAME DE LING OPNS. PAND A DAME DE LING OPNS. ALTERING CASING DAME DE LING OPNS. PAND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON REPAIRED REPA	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab tl ad. Start pumpin	ALTERING CASING LING OPNS. PAND A DAND A DAN
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON REPORT REPORT REPORT ACID REPORT ACID REPORT REPORT ACID REPORT REPOR	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab tl ad. Start pumpin	ALTERING CASING LING OPNS. PAND A DAND A DAN
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of Estimated Start Date: MIRU pulling unit. In Drop 3000# spot cont PBTD' 5900'-4539'. pump and FG/steel roll in the proposed of the pump and FG/steel roll in the proposed of the pump and FG/steel roll in the pump and FG	PLUG AND ABANDON REPORT REPORT REPORT ACID REPORT ACID REPORT REPORT ACID REPORT REPOR	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B" tbg. Tag PBT E HCL w/ 10% M U swab. Swab tl ad. Start pumpin e best of my knowlocd guidelines	ALTERING CASING LING OPNS. PAND A DAND A DAN
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON REPARED COMPL CHANGE PLANS COMPL COMPLETE COMPL COMPLETE COMPL COMPLETE COMPLITE COMPLETE COMPLETE COMPLETE COMPLETE COMPLETE COMPLETE COMPLET	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B' tbg. Tag PBT E HCL w/ 10% M U swab. Swab to ad. Start pumpin De best of my know HOCD guidelines	ALTERING CASING LING OPNS. PAND A DATE 09/14/2010
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON REPARED COMPL CHANGE PLANS COMPL COMPLETE COMPL COMPLETE COMPL COMPLETE COMPLITE COMPLETE COMPLETE COMPLETE COMPLETE COMPLETE COMPLETE COMPLET	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B' tbg. Tag PBT E HCL w/ 10% M U swab. Swab to ad. Start pumpin De best of my know HOCD guidelines	ALTERING CASING LING OPNS. PAND A DATE AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of estimated Start Date: MIRU pulling unit. In Drop 3000# spot content PBTD' 5900'-4539', pump and FG/steel round in the proposed of the period of t	PLUG AND ABANDON REPAIRED REP	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT THER: all pertinent det 1103. For Multip B" tbg. Tag PBT EHCL w/ 10% M U swab. Swab to ad. Start pumpin The best of my know	ALTERING CASING LING OPNS. PAND A DATE 09/14/2010 ALTERING CASING ALTERING CASING DATE 09/14/2010 ALTERING CASING DATE DATE ALTERING CASING DATE 09/14/2010 Telephone No. (432)689-5200
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: 13. Describe proposed or estimated date of start diagram of proposed of the content of the co	PLUG AND ABANDON REPAIRED REP	EMEDIAL WORK OMMENCE DRIL ASING/CEMENT OTHER: all pertinent det 1103. For Multip B' tbg. Tag PBT E HCL w/ 10% M U swab. Swab to ad. Start pumpin De best of my know HOCD guidelines	ALTERING CASING LING OPNS. PAND A DATE 09/14/2010