Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
D	ergy, Minerals and Natural Resources	October 13, 2009
District I  1625 N. French Dr., Hob P. C. III		WELL API NO. 30-025-39840
1201 W Grand Ave. Artesia NM 88210	L CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Aztec, SM 87410 District IV	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr , Santa OBBSOCD 87505		
SUNDRY NOTICES ANI		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR USE "APPLICATION FO	PRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	REEMIN (FORM C-101) FOR SOCI	Crossroads 22 State
1. Type of Well: Oil Well 🗵 Gas Well	l 🗌 Other	8. Well Number 3H
2. Name of Operator		9. OGRID Number
Marshall & Winston, Inc.  3. Address of Operator	1000000	14187 10. Pool name or Wildcat
<u>-</u>	Jarra 2 70710 0880	Flying M Abo
P. O. Box 50880, Midland, T	exas /9/10-0000	Flying H Abo
Unit Letter C: 400 feet from the North line and 1980 feet from the West line		
Section 22 Township 9S Range 33E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	4359' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTI	ON TO:	SSEQUENT REPORT OF:
NOTICE OF INTENTION PERFORM REMEDIAL WORK ☐ PLUG	AND ABANDON   REMEDIAL WOR	
	<u> </u>	RILLING OPNS. P AND A
	PLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE		_
		,
OTHER:	OTHER:	nd give portinent dates, including estimated date
13. Describe proposed or completed ope	rations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed ope of starting any proposed work). SEE</li> </ol>	rations. (Clearly state all pertinent details, as ERULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed ope	rations. (Clearly state all pertinent details, as ERULE 19.15.7.14 NMAC. For Multiple Co	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
<ol> <li>Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion</li> </ol>	rations. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Con.	ompletions: Attach wellbore diagram of
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3.	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1	ompletions: Attach wellbore diagram of  0. Drill hole to 423'. Ran 10 jts
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. § 13 3/8", 48#, J-55, ST&C csg	rations. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/13. Set @ 420'. Cmt w/ 450 sx Programmer.	ompletions: Attach wellbore diagram of .0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ½#/sk
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. § 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1  g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2	ompletions: Attach wellbore diagram of .0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + 1/4#/sk .24 hrs. NU & test BOP equip to
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT	ompletions: Attach wellbore diagram of .0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ½#/sk .24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 120 sx to Section 1000 sx 50:50 Poz Circ 120 sx 50:50 Poz Circ 1	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33	ompletions: Attach wellbore diagram of .0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ½#/sk .24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 9:36 AM, 08/08/10. Circ 618	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 9:36 AM, 08/08/10. Circ 618	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 9:36 AM, 08/08/10. Circ 618	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 9:36 AM, 08/08/10. Circ 618	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{9}{2}\$  13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra lead w/ 1000 sx 50:50 Poz Ci 9:36 AM, 08/08/10. Circ 618 Test csg to 1000#. Reached T	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/17.  G. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof.	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Circ 9:36 AM, 08/08/10. Circ 618	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{9}{2}\$  13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra lead w/ 1000 sx 50:50 Poz Ci 9:36 AM, 08/08/10. Circ 618 Test csg to 1000#. Reached T	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/17.  G. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof.	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{9}{2}\$  13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra lead w/ 1000 sx 50:50 Poz C. 9:36 AM, 08/08/10. Circ 618 Test csg to 1000#. Reached T	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:	ompletions: Attach wellbore diagram of a.0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. eep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{9}{2}\$  13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra lead w/ 1000 sx 50:50 Poz Ci 9:36 AM, 08/08/10. Circ 618 Test csg to 1000#. Reached T	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:	ompletions: Attach wellbore diagram of a.0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. eep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Rate lead w/ 1000 sx 50:50 Poz Celloflake. Circ 618 Test csg to 1000#. Reached Test csg to 1000#.	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Cont.  Spud 17 ½" hole @ 10 PM, 07/27/19. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:	ompletions: Attach wellbore diagram of a.0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk et hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. ep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{9}{2}\$  13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ra lead w/ 1000 sx 50:50 Poz C. 9:36 AM, 08/08/10. Circ 618 Test csg to 1000#. Reached T	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Spud 17 ½" hole @ 10 PM, 07/27/1 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 2 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:	ompletions: Attach wellbore diagram of a.0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. eep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Rate lead w/ 1000 sx 50:50 Poz Celloflake. Circ 618 Test csg to 1000#. Reached Test csg to 1000#. Reached Test csg to 1000#. Reached Test csg to 1000#. Spud Date:  O7/27/10  I hereby certify that the information above is SIGNATURE	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Cont.  Spud 17 ½" hole @ 10 PM, 07/27/17 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT class C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:  Rig Release Date:  TITLE Engineer	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. ep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Rate lead w/ 1000 sx 50:50 Poz Celloflake. Circ 618 Test csg to 1000#. Reached Test csg to 1000#.	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Cont.  Spud 17 ½" hole @ 10 PM, 07/27/17 g. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT class C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:  Rig Release Date:  TITLE Engineer	ompletions: Attach wellbore diagram of a.0. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk et hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. ep to drill lateral.
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. \$\frac{1}{2}\$ 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Ralead w/ 1000 sx 50:50 Poz Clead w/ 1000 sx 50:50 Poz Clead w/ 1000#. Circ 618 Test csg to 1000#. Reached Test csg to 1000#. Test csg to 1000#. Test csg to 1000#.	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equation 17 ½" hole @ 10 PM, 07/27/19. Set @ 420'. Cmt w/ 450 sx Prof. PD @ 9 AM, 07/29/10. WOC 20 an 103 jts 9 5/8", J-55, 40 & 36#, LT lass C + additives. Cmt tail w/ 33 sx cmt to surf. WOC 24 hrs. NU D @ 8932' @ 4:20 PM, 08/27/10. Prof. Rig Release Date:    Rig Release Date:	O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ½#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt 0 sx Class C + additives. PD @ & test BOP equipment to 3000#. ep to drill lateral.  ge and belief.  DATE 09/23/10  par-win.com PHONE: 432-684-6373
13. Describe proposed or completed ope of starting any proposed work). SEE proposed completion or recompletion  MIRU J.W. Drilling Rig #3. Section 13 3/8", 48#, J-55, ST&C csg Celloflake. Circ 120 sx to sur 2000#. Test csg to 2000#. Rate lead w/ 1000 sx 50:50 Poz Celloflake. Circ 618 Test csg to 1000#. Reached Test csg to 1000#. Reached Test csg to 1000#. Reached Test csg to 1000#. Geached Test csg to 1000#. Test csg to 1000#. Test csg to 1000#. Test csg to 1000#.	rations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. For Multiple Con.  Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. Equations. (Clearly state all pertinent details, at RULE 19.15.14 NMAC. (Clearly state all pertinent details,	ompletions: Attach wellbore diagram of  O. Drill hole to 423'. Ran 10 jts em Plus w/ 2% CaCl + ¼#/sk 24 hrs. NU & test BOP equip to C & STC csg. Set @ 4036'. Cmt O sx Class C + additives. PD @ & test BOP equipment to 3000#. ep to drill lateral.  DATE 09/23/10  mar-win.com PHONE: 432-684-6373