RECEIVED

Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I — Lr 2 Energy, Minerals and Natural Resources	WELL API NO.
1625 N French Dr , Hobbs, NM 88240 District II HOBBSOCD CONSERVATION DIVISION	30-025-31264
1301 W Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 Sonto Eq. NM 97505	STATE FEE
District IV 1220 S St Francis Dr, Santa Fe, NM	6. State Oil & Gas Lease No.
87505	B-4119
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	West Lovington Unit (26753)
PROPOSALS) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other	80
2. Name of Operator	9. OGRID Number
Chevron Midcontinent, L.P.	241333
3. Address of Operator	10. Pool name or Wildcat
#15 Smith Rd., Midland, Tx 79705	Lovington; Upper San Andres, West
4. Well Location	
Unit Letter M: 156 feet from the South line and	15feet from theWestline
26 5	
Section 4 Township 17-S Range 36-E	NMPM Lea County
11. Elevation (Snow whether DR, RRD, R1, GR, etc.	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attach	ed)
Pit Location: UL M Sect 4 Twp 17S Rng 36E Pit type Steel Depth to Groundwater	Distance from nearest fresh water well Over 1000'
Distance from nearest surface water Below-grade Tank Location ULSectTw	p;
156 feet from the South line and 15 feet from the West line	
	and the second of the second o
	•
12 Check Appropriate Box to Indicate Nature of Notice	Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO: SUE	
	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR PULL OR ALTER CASING ☐ MULTIPLE ☐ CASING TEST A	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR PULL OR ALTER CASING ☐ MULTIPLE ☐ CASING TEST A	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER.	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND d give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND Id give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 7. 9/2	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND d give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DE PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ID ILLING OPNS PLUG AND ABANDONMENT ILLING ABANDONMENT ILLING ABANDONMENT ILLING ABANDONMENT ILLING ABANDONMENT ILLING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Spot 25sx Cmt plug from 3150'-2950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 3150'-1950' (T. Salt) est	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND PLUG AND ABANDONMENT PLUG AND ABANDONMENT ND PLUG AND ABANDONMENT ND PLUG AND ABANDONMENT ND PLUG AND ABANDONMENT PLUG ABANDONMENT PLUG AND ABANDONMENT PLUG ABANDONM
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Opot 25sx Cmt plug from 3150'-2950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND PLUG AND ABANDONME
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Spot 25sx Cmt plug from 3150'-2950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface)	SEQUENT REPORT OF: RK ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ND d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 0/10 Install Dry Hole Marker. red for plugging of well bore only. ry under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) nay be found at OCD Web Page under
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Opot 25sx Cmt plug from 3150'-2950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND STATE OF THE PLUG AND ABANDONMENT Of give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 10/10 Install Dry Hole Marker. The formulation of the proposed completion of the plugging of well bore only. The proposed completion of the proposed completion of the plugging of well bore only. The proposed completion of the proposed completion of the plugging of well bore only. The proposed completion of the proposed completion of the plugging of the
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRE PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit a general permit	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND STATE OF THE STATE O
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMEDIAL WORK PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 3150'-2950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my knowledge.	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT Indigine pertinent dates, including estimated date ttach wellbore diagram of proposed completion O/10 Install Dry Hole Marker. The for plugging of well bore only, y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) The found at OCD Web Page under The state of the plugging of the
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRE PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit a general permit	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 7 9/2 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Sait) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Sait) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my kinewied grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE MANAGEA Type or print name Timmy BAGLEY E-mail address: Sunsetwellse	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT Indigine pertinent dates, including estimated date ttach wellbore diagram of proposed completion 10/10 Install Dry Hole Marker. The for plugging of well bore only, y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) In a be found at OCD Web Page under www.mennd.space.pmps.cod. The formula of the foundation of the control of the contro
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRE PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (B Salt) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Salt) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE MANAGEM TOTHER TITLE MANAGEM TITLE MANAGEM TITLE MANAGEM TITLE MANAGEM TOTHER TITLE MANAGEM TITLE MANAGEM TOTHER TOTHER TOTHER TITLE MANAGEM TOTHER TOTH	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT Indigine pertinent dates, including estimated date ttach wellbore diagram of proposed completion 10/10 Install Dry Hole Marker. The for plugging of well bore only, y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) In a be found at OCD Web Page under www.mennd.space.pmps.cod. The formula of the foundation of the control of the contro
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMENT JOB PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A correcompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 2. 9/17/10 Tag CIBP@4657 & Spot 25sx Cmt plug from 4657-4467 (S. Andres) 3. 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 3150-2950 (B. Salt) est 5. 9/17/10 Spot 25sx Cmt plug from 2150'-1950 (T. Salt) est 6. 9/20/10 Perf@465 Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines a general permit SIGNATURE Title MANAGE Type or print name Timmy BAGLEY E-mail address: sunsetwellse (This space for State use)	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: OTHER. 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. 9/16/10 Notified OCD 24 hrs prior to MIRU to P & A equipment. 7 9/2 2 9/17/10 Tag CIBP@4657' & Spot 25sx Cmt plug from 4657'-4467' (S. Andres) 3 9/17/10 Displace Hole w/MLF, 9.5# Brine w/25# Gel P/BBL 4. 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Sait) est 5 9/17/10 Spot 25sx Cmt plug from 2150'-1950' (T. Sait) est 6 9/20/10 Perf@465' Spot 55sx Cmt plug@515'-Surf WOC&Tag (Shoe/Fr Wtr. Surface) I hereby certify that the information above is true and complete to the best of my kinewied grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE MANAGEA Type or print name Timmy BAGLEY E-mail address: Sunsetwellse	ALTERING CASING ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT ILLING OPNS PLUG AND ABANDONMENT ND ABANDONMENT Indigine pertinent dates, including estimated date ttach wellbore diagram of proposed completion 10/10 Install Dry Hole Marker. The for plugging of well bore only, y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) In a be found at OCD Web Page under www.mennd.space.pmps.cod. The formula of the foundation of the control of the contro