		•		
Submit 3 Copies To Appropriate District	State of New Mexi	ico		Form C-103
Office	Energy, Minerals and Natura	l Resources		May 27, 2004
District I 1625 N French Dr., Hobbs, NM 88240			WELL API NO.	
District II	OIL CONSERVATION [VIVISION 3	30-025-34626 🖊	
District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artes R 682 Ion District III	1220 South St. Franci	ic Dr	5. Indicate Type of	
District III 1000 Rio Brazos Rd, Aztec, NM 874103 0 2011 District IV	1220 South St. Flanc	D BI.	STATE	FEE
District IV SEP 30 L4	Santa Fe, NM 875	05 6	5. State Oil & Ga	s Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	مار			
87505	AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS T	TO DRILL OR TO DEEPEN OR PLUG			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Red Hills Unit	_
PROPOSALS.) 1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other 🔲			8. Well Number	
1. Type of well: Oil well 📋 Gas v			004	-
2. Name of Operator			9. OGRID Numb	er
•			162683	
Cimarex Energy Co. of Colorado				
3. Address of Operator			10. Pool name or Wildcat	
600 N. Marienfeld, Ste. 600; Midland	I, TX 79701		Red Hills; Devon	lian
4. Well Location				
SHL Unit Letter N : 454	feet from the <u>South</u> lin	ne and <u>1500</u>	feet from the	<u>West</u> line
	25S Range <u>33E</u>	NMPM	County	Lea
	Elevation (Show whether DR, F	RKB, RT, GR, etc.)	Since	· ···································
	37' GR		0	and the second second
Pit or Below-grade Tank Application or Close				
Pit type Depth to Groundwater		er well Di	stance from nearest s	surface water
	low-Grade Tank: Volume		uction Material	
12. Check Appro	opriate Box to Indicate Nat			
NOTICE OF INTEN	ITION TO:	SUBS	EQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILI	LING OPNS	PANDA
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	јов 🗌	1
OTHER: Plug back and	d TA for Wolfcamp RC 🛛	OTHER [.]		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompletion.				
Well currently completed in the Devoniar	n with perfs @ 17468-17567' wi	ith Howo PLS packe	r @ 16910.' Well	shut-in since 5/09.
Cimarex proposes to abandon Devonian a	and Morrow and run MIT for Te	mporary TA to allow	w for partner app	roval, rig scheduling, frac
dates, completion and production report		. ,		
• Acidize with 1000 gal 15% HCL double	-inhibited.			
• MIRU pulling unit. ND WH, NU BOP. I		5910'		
• Scan tbg out of hole. RIH w 3 1/2" gauge ring to 17450'. Set CIBP @ 17400.'				
Load hole and break circulation w 9#1			cer. 10.5 bbl Clas	s H 17400-16775.' PU to 🕠
16500' and reverse clean.		0		
	d nlug @ 1500-14861 ' PU to 1	4300' and reverse o	lean.	
 Spot 25 sx Class H cement for balanced plug @ 1500-14861.' PU to 14300' and reverse clean. Pressure test casing to 500 psi for 30 minutes and call BLM to witness test 24 hours prior. 				
• TOH w unnecessary tbg leaving 14300' in hole. Circulate and condition packer fluid.				
• TOH w diffecessary tog leaving 14300	in hole. circulate and condition	on poeker naid.		1
Please see attached WBD. Request TA p	pending Wolfcamp recompletio	n (sundry to BC to b	oe sent under sep	arate cover).
Please see attached WDD. Request in p	pending woned inpresentation			
I hereby certify that the information abov	a is true and complete to the best	st of my knowledge	and belief I furth	er certify that any nit or below-
grade tank has been/will be constructed or closed	according to NMOCD guidelines	l, a general permit 🗌 o	r an (attached) alteri	native OCD-approved plan \Box .
			`	
SIGNATURE Vatahullu	ritleRe	gulatory Analyst	DATE	September 29, 2010
Type or print name Natalie Krueger	() email address: nkru	eger@cimarex.com	Telephone	No <u>. 432-620-1936</u>
For State Use Only				
APPROVED BY:	TITLE	2TAH	MGP	DATE 0-4-10
Conditions of Approval (if any):	1			N
				V S

0

24 hours prior to running the TA pressure test.	Conditions of
r to running	Approval:
the TA pres	Notify OCD
sure test.	Conditions of Approval: Notify OCD district office

Red Hills Unit # 4 Temporarily Abandon Procedure API # 3002534626000 454' FSL & 1500' FWL

Section 32, T25S, R33E Lea County, Mew Mexico

<u>Well Data</u> :	
KB	27' above GL
TD	17675'
PBTD	17628'
Casing	20" 94 & 106 # J-55 @ 892'. Cmtd w/ 1700 sx. Cmt circ.
	13-3/8" 72 & 68 # P-110 and J-55 @ 4880' Cmtd w/ 2745 sx. Cmt circ.
	9-5/8" 53.5 # P110 @ 13002' Cmtd w/ 1475 sx.
	7" 38 # P110 @ 12750-17046' Cmtd w/ 585 sx.
	4-1/2" 13.5 # P-110 @ 16827-17675'. Cmtd w/ 100 sx. Full Returns.
Perfs	Devonian (17468' –72', 17504'-22', 17530'-67')
BHT	268° F

Note: Will need lift sub and 17 joints of RTS-6 tubing for job (See Tubing Detail). Will need 20 joints of 2 3/8" J-55 tubing and crossover to run into 4 $\frac{1}{2}$ " liner.

<u>Procedure:</u> Before RU Check for Permit Status Notify OCD 24 hr before RU for Setting CIBP.

- 1. Before RU perform 1000 gal acid job W/ 15% HCL double inhibited.
- 2. MIRU pulling unit. ND WH, NU BOP. Release Howco PLS Packer@ 16910'.
- 3. Pick up extra tubing and lower packer to 17450'.
- 4. Scan tubing out of hole.

- 5. RIH W/ Gauge Ring to 17,450' (confirm gauge ring size W/ wireline company).
- 6. TIH W/ 4 ¹/₂" Wireline set CIBP & set @ 17400'.
- TIH W/ 2 7/8" Tubing to 16775' W/ 20 jts 2 3/8" Tailpipe to get in liner. Load hole and brake circulation W/ 9 # brine W/ packer fluid and O2 scavenger. Pump 10 BBL fresh water spacer. Spot 10.5 BBL Class H Cement from 17,400' – 16,775'.
- 8. Pull up to 16,500' and Reverse Clean.

- 9. Pull tubing up to 15000'. Pump 10BBL fresh water spacer. Spot 25 sack Class H Cement for balance Plug from 15,000 14,861'.
- 10. Pull up to 14300' and reverse clean.
- 11. Perform Casing Integrity test by pressuring to 500 psi for 30 min and charting for OCD. **NOTE: Call OCD to witness Casing Integrity Test.**
- 12. TOH W/ unnecessary tubing, laying down in singles, leaving +/- 14,300' in hole. RDMO.
- 13. Circulate and condition packer fluid.
- 14. Submit necessary regulatory paperwork.



