

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87400
District IV
1220 S St Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

RECEIVED

SEP 30 2010

HOBBSD

CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-08769
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Seven Rivers Queen WF, North
8. Well Number 3
9. OGRID Number 005380
10. Pool name or Wildcat Eunice; Seven Rivers-Queen, South
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator XTO Energy, Inc.
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701
4. Well Location Unit Letter <u>F</u> : <u>1980'</u> feet from the <u>North</u> line and <u>1980'</u> feet from the <u>West</u> line Section <u>4</u> Township <u>22S</u> Range <u>36E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Acid Stimulation ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/2/10 MIRU. POOH & scan 126 jts 2-3/8" 4.7# J-55 EUE 8rd prod tbg GB jts 15,17,53,114 & 122 FS due to wear. RB jts 124-126 FS due to wear. RD.

9/3/10 Move in & rack 137 jts 2-7/8" 6.5# L-80 EUE 8rd WS. PU & RIH w/notch collar, 23 jts 2-7/8" L-80 WS, 5-1/2" csg scraper & 100 jts 2-7/8" L-80 WS. RD. Tag PBTD @ 3,900'. POOH & LD notch collar & csg scraper. PU & RIH w/5-1/2" tens pkr & 100 jts 2-7/8" L-80 WS.

Procedure Cont'd. on Next Page

Spud Date:

9/02/10

Rig Release Date:

9/10/10

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kristy Ward TITLE Regulatory Analyst DATE 9/23/10

Type or print name Kristy Ward E-mail address: kristy_ward@xtoenergy.com PHONE 432-620-6740

For State Use Only

APPROVED BY [Signature] TITLE State Rep DATE 10-4-10

Conditions of Approval (if any):

OK

Seven Rivers Queen WF, North #3
Acid Stimulation Cont'd.

- 9/07/10 RIH & set pkr @ 3,714'. RU Petro-Plex acid equip. Load TCA w/55 bbls 2% kcl wtr. Acidize Queen perfs & OH fr 3,762'-3,900' w/3,500 gal 15% 85/15 acid/xylene down 2-7/8" 6.5# L-80 EUE 8rd WS. Pmpd 3,000# RS in 3 stages w/good diversion. Flushed acid w/90 bbls 2% kcl wtr. RD. RIH w/2-7/8" swab cups. Rec 4 BLW w/0% oil cut. RD.
- 9/08/10 RIH w/notch collar & 120 jts 2-7/8" 6.5# L-80 EUE 8rd WS. Tag salt @ 3,896'. Wash salt to PBTd @3,900'. RIH w/2-7/8" swab cups. RD.
- 9/09/10 RIH w/125 jts 4.7# J-55 EUE 8rd prod tbg. RD. Start in hole w/pump & rods.
- 9/10/10 RIH w/2-3/8" OEMA, 2-3/8" SN, 115 jts 2-3/8" 4.7# J-55 EUE 8rd prod tbg & 10 jts 2-3/8" J-55 prod tbg. ND BOP. NU WH. RIH w/2.0"x1.25"x12'x3' RXBC w/4'GA, RHBC, 7/8" STBlz sub, 152 - 3/4" D-90 rods, 2-3/4" D-90 subs & 1-1/2" x 22' SMPR. Load tbg w/11 bbls 2% kcl wtr & 10 gal paraffin solvent. RD. RDMO PU. RWTP.