

United States Department of the Interior

www.blm.gov/nm/st/en.html

BUREAU OF LAND MANAGEMENT Pecos District Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292

OFFICIAL FILE COPY INAMERICA

In Reply Refer To: NM-94095 3162.4 (P0220)

OCT 1 3 2010 OCT 15 2010 HOBBSOCD

Yates Petroleum Corporation 105 South Fourth Street Artesia, NM 88210

Gentlemen:

Your Applications for Permit to Drill (APDs) the attached referenced wells have expired because drilling has not commenced within two years as per Onshore Order #1.

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM, so we may correct our records.

If you wish to drill these wells at a later date, please submit a complete application (1 original and 3 copies for each well) to this office. Since the original APDs have expired, the resubmitted APDs will be subject to all the processing requirements including the 30-day posting requirement. Please note on the resubmitted APDs that they were previously approved and we will review the expired files for information which will help expedite the processing. If you have any questions please contact Betty Hill at (575) 234-5937.

Sincerely,

/s/ JD Whitlock Jr

Don Peterson **FOR** Assistant Field Manager Lands & Minerals

1 Attachment

bcc: NMP0222, I&E HFS NMOCD, Hobbs



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St Carlsbad New Mexico 88220-6292 www blm gov/nm



In Reply Refer To. NMNM 94095

July 24, 2009

Memo to File:

Reference IBLA 2006-288, Intrepid Potash vs BLM and Yates Petroleum Corporation

9/28/2007 - IBLA granted Stay on drilling of Caper wells (listed-below) 9/29/2008 - IBLA ended Stay

On advice of counsel, the two year limit was tolled during the period September 28, 2007 through September 29, 2008. Therefore, the following Applications for Permit to Drill do not expire until August 18, 2010:

Yates Petroleum Corp., Lease No. NMNM 94095

Yates Petroleum Corp., Lease No. NMNM 94095	Al a Charl
30-025-38092	30-025-39097
Caper BFE Federal #7	Caper BFE Federal #12
Surface Hole: 330 FNL & 1650 FEL,	Surface Hole: 2310 FNL & 2310 FEL,
Section 17, T.21S., R.32E.	Section 17, T.21S., R.32E.
	Bottom Hole: Same
Bottom Hole: Same 3p-025-38043 Caper BFE Federal #8 Surface Hole: 330 FNL & 2310 FWL,	30-025-38098
Caper BFE Federal #8	Caper BFE Federal #13
Surface Hole: 330 FNL & 2310 FWL,	Surface Hole: 2310 FNL & 990 FEL,
Section 17, T.21S., R.32E.	Section 17, T.21S., R.32E.
Bottom Hole: Same	Bottom Hole: Same 30.025-38099
30-025-38094	
Caper BFE Federal #9	Caper BFE Federal #14
Surface Hole: 990 FNL & 990 FWL,	Surface Hole: 2310 FSL & 330 FEL,
Section 17, T.21S., R.32E.	Section 17, T.21S., R.32E.
Bottom Hole: Same	Bottom Hole:
30.025-38095	30.025-38100
Caper BFE Federal #10	Caper BFE Federal #15
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL,	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL,
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL,
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL,	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL,	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.
Caper BFE Federal #10 Surface Hole: 2310 FNL & 990 FWL, Section 17, T.21S., R.32E. Bottom Hole: Same 30.025-38096 Caper BFE Federal #11 Surface Hole: 2310 FNL & 2310 FWL, Section 17, T.21S., R.32E.	Caper BFE Federal #15 Surface Hole: 1650 FSL & 990 FWL, Section 17, T.21S., R.32E.