Form 3160-5	UNITED		OCT 15	2010	FORM APPROVE		
(February 2005)	DEPARTMENT OF	F THE INTERIO	R 「 m へのひら	OCD	OMB No. 1004-013 Expires: March 31, 2		
	BUREAU OF LANI) MANAGEMEN	MODDA	900	5 Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS					NMLC 0 064194		
Do not use this form for proposals to drill or to re-enter an					6 If Indian, Allottee or Tribe Na		
abandoned well. Use Form 3160-3 (APD) for such proposals.					o in middle, shottee of Tribe Name		
	UBMIT IN TRIPLICATE			-	7. If Unit of CA/Agreement, Na	me and/or No.	
1. Type of Well							
					8. Well Name and No.		
Oil Well Gas Well Other					SCJ Federal #1		
2. Name of Operator					9. API Well No.		
Snow Oil & Gas Inc					30-025-31717		
3a. Address P.O. Box 1277 Andrews, Texas 79714 3b. Phone No. (include area code) (432) 524-2371					10. Field and Pool or Exploratory Area NE Lea Delaware		
P.O. Box 1277 Andrews, Texas 79714 (432) 524-2371 4. Location of Well (Footage, Sec., T., R, M., or Survey Description)					11. Country or Parish, State		
Sec 9, T20S, R34E 660' FNL 330' FEL					Lea		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
Acidize Deepen Production (S)					art/Resume) Water Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat		Reclamation	Well Integr		
Casing Repair New Construction Recomplete					Other		
Subsequent Report Change Plans Plug and Abandon Temporarily A							
Final Abandonment							
Notice	Convert to Injection	Plug Back		Water Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)							
Snow Oil & Gas Inc (Snow) is proposing the re-completion of the subject well to the Yates formation. Snow will do the following:							
Test the casing integrity that is currently in hole and determine the procedure for repair, if needed. Snow will set a cast iron bridge plug at 5610' and cap with 40' cement. Snow will run GR-CCL log across the Yates Formation at the 4000'-3000' interval and perforate said formation at approximately 3400'-3700' interval and swab and stimulate as needed. There will be no additional surface use needed beyond current drill site and production pad.							
SEE ATTACHED FOR							
CONDITIONS OF APPROVAL							
PET witness required							
14. I hereby certify that the fore	going is true and correct.			f	·		
Name (Printed/Typed) Joe Lindemood			Title Agent	,			
1							
Signature Date August 13, 2010 THIS SPACE FOR FEDERAL OR STATE OFF OF DESCRIPTION DATE.							
Approved by Title Title Date							
Conditions of approval, if any see attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Office /s/ Dustin Winkler							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly DIFFERULOFOLYARD AREQUIPMENT ASSETS United States any false, fictitious or fraudulent statements or representations as to any matter within its jurnsdic OARLSBAD FIELD OFFICE							

(Instructions on page 2)

PETROLEUM ENGINEER OCT 1 8 2010



Snow Oil & Gas Inc. NMLC-064194 – SCJ Federal #1 API: 30-025-31717 Lea County, New Mexico

RE: Recomplete - Conditions of Approval

No surface disturbance beyond originally approved well pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

Work to commence within 90 days of approval.

Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Lea County, call 575-393-3612.

2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

Appropriate plugging below the perfs shall be done when abandoning the wellbore.

Submit subsequent report and completion report with well test once work is completed.

DHW 101310