

Submit 1 Copies To Appropriate District Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

RECEIVED
OCT 20 2009
OIL CONSERVATION DIVISION
HOBBS
State of New Mexico
Energy, Minerals and Natural Resources
South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

WELL API NO. 30-025-20610
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Bagley
8. Well Number 1
9. OGRID Number 151323
10. Pool name or Wildcat N. Bagley Permo Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Pride Energy Company

3. Address of Operator
P O. Box 701950, Tulsa, OK 74170-1950

4. Well Location
Unit Letter A : 560 feet from the North line and 560 feet from the East line.
Section 9 Township 11S Range 33E NMPM Lea County NM

11 Elevation (Show whether DR, RKB, RT, GR, etc)
4,273' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTH: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of
C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/oed

July 1, 2008: Plugged and abandoned this well by doing the following.

1. Gave OCD 24 hours notice prior to commencing plugging operation.
2. RUPU, RIII w/ tbg, Spot 35' cement plug w/dump bailer on top of 8 5/8" casing stub @ 827'. WOC, tag plug.
3. Circulate hole w/9.5 ppg mud.
4. Spot a 100' cement plug across bottom of 13 3/8" casing from 307' to 407', WOC 4 hrs, tag cement plug. Set a 10 sk cement plug at surface.
5. Cut off and weld plate on casing. Erect standard 4' P&A marker.
6. Restore Location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Matthew L. Pride TITLE

By: Pride Production Co., INC
Title: General Partner
By: Matthew L. Pride
Title: President

DATE: 10/19/10

Type or print name Matthew L. Pride

E-mail address: mattp@pride-energy.com

Telephone No. 918-524-9200

For State Use Only

APPROVED BY: [Signature] TITLE STAFF MGR DATE 10-21-10
Conditions of Approval (if any).