Form C-103 Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-36130 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE FEE X Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Brabant. 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 8. Well No. OXY USA WTP Limited Partnership 192463 3. Address of Operator 9. Pool name or Wildcat P.O. Box 50250 Midland, TX 79710-0250 Undsq. Brunson Drinkard-Abo, South 4. Well Location 1980 Unit Letter north line and_ 1980 feet from the _ feet from the___ east line Township 225 38E **NMPM** Range County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3389 11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND X PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB

THER:

OTHER:

OTHER:

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagrams of proposed completed until Bore. **PULL OR ALTER CASING** OTHER: 10/03/2003 Flowed well to pit pumped 40 bbls down tbg and 50 bbls csg. NDWH NU BOP RIH tagget 10/03/2003 pumped 20sx salt gel. Spot 25sx cmt on top of CIBP. POOH to 7420' spot 50sx cmt. SION 10/04/2003 RIH tagged cmt plug @ 7223'. CH w/ salt gel and spot 25sx cmt on top of plug. P00H, to 6232 spot 25sx cmt. POOH to 5500 spot 25sx cmt. POOH to 3283 spot 25sx. WOC RIH tagged cme @ 2986 1 2004 POOH to 1355 spot 35sx cmt. SI till Monday RLUL!VED Hobbs 10/07/2003 RIH tagged cmt @ 920'. ND BOP, set 10sx surface plug. RDMO OCD 10/11/2003 Cut off wellhead and anchors and installed dry hole marker I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE___ _ TITLE Sr. Regulatory Analyst __ DATE_ Type or print name David Stewart Telephone No. 432-685-5717

(This space for State use)

Conditions of approval, if any

OC FIELD REPRESENTATIVE II/STAFF MANAGER