Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I Ene	rgy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210		WELL API NO. 30-025-06703
	IECONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741 SEP 27 2010 Santa Fe, NM 87505		STATE FEE
		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NHOBBSO	CD	N/A
SUNDRY NOTICES ANI (DO NOT USE THIS FORM FOR PROPOSALS TO D	O REPORTS ON WELLS RILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FO PROPOSALS.)	R PERMIT" (FORM C-101) FOR SUCH	M.E. Wantz
1. Type of Well: Oil Well Gas Well	Other	8. Well Number # 9
2. Name of Operator		9. OGRID Number 217817
ConocoPhillips Company		10 P 1
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 51810 Midland, Tx 79710		
4. Well Location Unit Letter J : 1980		1980 feet from the East line
Section 21	Township 21S Range 37E	NMPM County Lea
11. Ele 3448	vation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropri	ate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION	ON TO: SUF	SEQUENT REPORT OF:
	AND ABANDON REMEDIAL WOF	
		ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIF	PLE COMPL	Т ЈОВ □
DOWNHOLE COMMINGLE		
DOTTITIOEE COMMITTOEE		
, -	OTHER: De	occumpleted = DALC
OTHER:		ecompleted — DHC In a give pertinent dates including estimated date.
OTHER: 13. Describe proposed or completed open	rations. (Clearly state all pertinent details, ar	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed open	ations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and to IH w/new 2 3/8" tubing and set at 6450. Pic.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and the state of the s	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	rations. (Clearly state all pertinent details, an RULE 19.15.7.14 NMAC. For Multiple Co. 1. r/scraper. Perforated 1 spf at 5710-17, 5763-6 ssure tested casing and shut down. TIH and to IH w/new 2 3/8" tubing and set at 6450. Pic.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	RULE 19.15.7.14 NMAC. For Multiple Co. RULE 19.15.7.14 NMAC. For Multiple Co. Assure Perforated 1 spf at 5710-17, 5763-6 Sisure tested casing and shut down. TIH and to the sum of the s	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang
OTHER: 13. Describe proposed or completed open of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	RULE 19.15.7.14 NMAC. For Multiple Co. RULE 19.15.7.14 NMAC. For Multiple Co. Assure Perforated 1 spf at 5710-17, 5763-6 Sisure tested casing and shut down. TIH and to the sum of the s	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	RULE 19.15.7.14 NMAC. For Multiple Co. All All All All All All All All All Al	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang ge and belief.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production.	RULE 19.15.7.14 NMAC. For Multiple Co. RULE 19.15.7.14 NMAC. For Multiple Co. Assure Perforated 1 spf at 5710-17, 5763-6 Sisure tested casing and shut down. TIH and to the sum of the s	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 68, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang ge and belief.
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production. Spud Date: I hereby certify that the information above is the SIGNATURE.	RULE 19.15.7.14 NMAC. For Multiple Co. All All All All All All All All All Al	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 58, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It up new pump, sinker bars, and rods. Hang ge and belief. DATE 9/22/2010 1.i.ams
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production. Spud Date: I hereby certify that the information above is to SIGNATURE Type or print name Donna Wiliams	RULE 19.15.7.14 NMAC. For Multiple Co. All Secretary state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Co. All Secretary Perforated 1 spf at 5710-17, 5763-65 saure tested casing and shut down. TIH and the sum of the secretary shows a second secretary to the second seco	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of 58, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It up new pump, sinker bars, and rods. Hang ge and belief. DATE 9/22/2010 1.i.ams
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production. Spud Date: I hereby certify that the information above is the SIGNATURE.	RULE 19.15.7.14 NMAC. For Multiple Code. All All All All All All All All All Al	de give pertinent dates, including estimated date impletions: Attach wellbore diagram of 58, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang ge and belief. DATE 9/22/2010 DIATE 9/22/2010 DATE 432-688-6943
OTHER: 13. Describe proposed or completed oper of starting any proposed work). SEE proposed completion or recompletion 6/14-9/3/2010: MIRU. TOH w/tubing. RIH w perfs with 2700 gls 15% NEFE HCl acid. Pre Cleanout out well to PBTD of 6472 (CIBP). R well on and returned to production. Spud Date: I hereby certify that the information above is to SIGNATURE Type or print name Donna Wiliams	RULE 19.15.7.14 NMAC. For Multiple Co. All All All All All All All All All Al	de give pertinent dates, including estimated date impletions: Attach wellbore diagram of 58, 5833-41, 5858-65, and 5921-31. Acidized tagged composite plug at 6305 and retrieved. It is new pump, sinker bars, and rods. Hang ge and belief. DATE 9/22/2010 DIATE 9/22/2010 DATE 432-688-6943