		···· • •• •••	
Submit 1 Copy To Appropriate District Office	ice State of INCW INEXICO		Form C-103
Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.	
District III1301 W. Grand Ave., Artesia, NM 88210District IIIDEC 18 20101000 Rio Brazos Rd., Azec, NM 87410District IV1220 S. St. ProBBSSIG1220 S. St. ProBBSSIG1220 S. St. ProBBSSIG1220 S. St. ProBBSSIG1220 S. St. ProBBSSIG		30-005-01100	
		5. Indicate Type of Lease STATE X FEE	
		/505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name	
		West Cap Queen Sand Unit	
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other		8. Well Number 10	
2 Name of Operator		9. OGRID Number	
2. Address of Operator Learning II, LP			247128 10. Pool name or Wildcat
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701		Caprock; Queen	
4. Well Location			
Unit Letter <u>O : (</u> Section 17	560 feet from the <u>S</u> Township 14S Ra	line and <u>19</u> inge 31E	080 feet from the E line NMPM CountyChaves Image: Co
Interview Interview <t< td=""></t<>			
	4118' GL		
12. Check At	ppropriate Box to Indicate N		Report or Other Data
-			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE			BSEQUENT REPORT OF:
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB
OTHER: Convert to injector	X	OTHER:	
13. Describe proposed or comple	ted operations. (Clearly state all I	pertinent details, ar	nd give pertinent dates, including estimated date
of starting any proposed worl proposed completion or reco		2. For Multiple Co	ompletions: Attach wellbore diagram of
1) POOH with production equipm			
 Make a bit/scraper run to TD. Run CIL. Run packer and test 	casing	· · · · ·	
4) Run composite plug. Run and		Condition	of Approval : Notify OCD Hobbs
5) Drill out 4" to TD.6) Run packer and injection tubing		office 24	hours prior to running MIT Test & Chart
7) Place well on injection per NM	OCD admin. Order WFX-872.	··· · · · · · · ·	
			jection Control Progam Manual
			be set within or less than 100 st injection perfs or open hole.
		or the uppermos	st injection pens of open noie.
Spud Date:	Rig Release Da	ite:	
	·	L	
I hereby certify that the information al	sove is true and complete to the be	est of my knowled	ge and belief.
. 0			-
SIGNATURE Ausa 4	funct TITLE Regula	tory Analyst	DATE_11/18/2010
Type or print name Lisa Hunt	E-mail address	: lhunt@celeroen	ergy.com PHONE: (432)686-1883
For State Use Only			
APPROVED BY:	Fighter TITLE ST	Af M	DATE //-18-10
Conditions of Approval (If any):	<u></u>		
/ [

• · ·

CELERO ENERGY



Well History: West Cap Queen Sand Unit #10

<u>8/55 - D&C:</u> Spot 250 Gals acid; frac with 10000 GCO & 10000 lbs sand. IP at 127 BOPD, 0-BWPD.

<u>6/60-Restim:</u> Frac with 1000 gals NE acid, 20000 gals GCO & 30000 lbs sand. 27+ BPM, 2400 psi. ISIP = 1800 psi.

6/08-Restim: Replaced 4' of 8-5/8" & 5-1/2". P-test and locate hole(s) at 196'-221'. Cement down 5-1/2" with 200 sx Cl C, 1.5 BPM, 215#--did not circulate cement on annulus. D-O and fell out of cement at 230'. Failed to P-test. Pump 150 sx Cl C down 5-1/2" at 1.2 BPM, 230#. Tag at 169', D-O and fell out of cement at 230'. Pull RBP, treat down tubing w/24 bbls xylene at 3 BPM, 772#. Swab down to 2600' and recovered 91 BW in 8-1/2 hours. Swab 2nd day-recovered 34 bbls at 1% oil cut. Frac with 17500 gals GW, 19000 lbs 20/40 Brady & 9000 lbs R-C sand at 15 BPM, 2319 psi, ISIP=1833 psi. SION--ran pump & rods.

Well History: West Cap Queen Sand Unit #10

(7-56) - Initial Completion: Orig comp thru perfs 2760' - 2770'. Treated perfs w/ 250 gals mud acid wash, 10,000 gals control-frac and 10,000 # sand. Flushed w/ LSE crude. IP: 84 BOPD.

(08-08) - Workover: TOOH w/ rods, pump, and 2 3/8" production tubing. Replaced wellhead. CO well to TD @ 2780' (6' of fill). Acidized Queen interval (2760' - 2770') w/ 500 gal toluene, 2500 gal 80/20 mixture of 7 1/2% NEFE acid and toluene, and 1000# rock salt @ 5 BPM and 2039 - 2200 psi STP. Swabbed load back. Ran 2 3/8" 4.7# J-55 production tubing and BHA. Returned well to production.