
Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
	nergy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NASS		WELL API NO. 35-025-35543
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87460 18 2010 District IV	1220 South St. Francis Dr.	STATE S FEE .
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fend BBSOC 87505		300649
SUNDRY NOTICES AN	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO	DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION I PROPOSALS.)	FOR PERMIT" (FORM C-101) FOR SUCH	Arrowhead Greyburg Unit
	ell Other	8. Well Number 337Y
2. Name of Operator		9. OGRID Number
XTO Energy Inc.		5380
3. Address of Operator	M. II. 1 T.V. 70701	10. Pool name or Wildcat Arouhand
200 Loraine Ste. 800	Midiand 1X. 79701	Greyburg San Andres
4. Well Location		
	t from theNorth line and1270_	
1	2S Range 36E NMPM	County Lea
11. E	levation (Show whether DR, RKB, RT, GR, e	etc.)
Pit or Below-grade Tank Application ☐ or Closure	· N	
		ance from nearest surface water N/A
		estruction Material
12. Check Approp	riate Box to Indicate Nature of Notice	ce, Report or Other Data
NOTICE OF INTENT	TION TO:	SUBSEQUENT REPORT OF:
	G AND ABANDON K	
	• • • • • • • • • • • • • • • • • • •	DRILLING OPNS 🗌 PAND A 🔀
PULL OR ALTER CASING MUL	TIPLE COMPL	MENT JOB 🔲 -
	TIPLE COMPL CASING/CEN	MENT JOB
OTHER:	OTHER:	
OTHER: 13. Describe proposed or completed op	OTHER:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion.	OTHER: perations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole N	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt.	OTHER: perations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. We see the second of the secon	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. We see the second of the secon	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work PUH. to 551' Circulate 75 sx Cmt.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT 2/	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work PUH. to 551' Circulate 75 sx Cmt.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Work Puh. to 551' Circulate 75 sx Cmt. The Oil Conservation Division III.	OTHER: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx · CmT • /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works. 5. PUH. to 551' Circulate 75 sx Cmt. The Oil Conservation Division Muse 24 hours prior to the beginning of the prior to the prior to the beginning of the prior to t	orher: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT 2/. St be notified f plugging operations.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works. 5. PUH. to 551' Circulate 75 sx Cmt. The Oil Conservation Division Muse 24 hours prior to the beginning of the prior to the prior to the beginning of the prior to t	orher: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT 2/. St be notified f plugging operations.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole Market 1. Set CIBP at 3667' Circulate 1. Set CIBP at 3667' C	orher: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT 2/. St be notified f plugging operations.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 330' edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole No. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works. 5. PUH. to 551' Circulate 75 sx Cmt. The Oil Conservation Division Muse 24 hours prior to the beginning of the prior to the prior to the beginning of the prior to t	orher: Derations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT 2/. St be notified f plugging operations.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works and the start of the beginning of the construction Division Mu 24 hours prior to the beginning of the start of the beginning of the start o	OTHER: Deterations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 330' edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works and the start of the beginning of the construction Division Mu 24 hours prior to the beginning of the start of the beginning of the start o	OTHER: Deterations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 330' edge and belief. I further certify that any pit or belowed or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole P. 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Words. 5. PUH. to 551' Circulate 75 sx Cmt. The Oil Conservation Division Mu 24 hours prior to the beginning of the segment o	OTHER: Deterations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CMT / Completions. St be notified f plugging operations. Strue and complete to the best of my knowledge of plugging to MOCD guidelines , a general permit of the coordinate of the coord	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date attach wellbore dates and give dates attach dates attached attached dates. Begin date and dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin date dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin dates attached dates. Begin dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin dates attached dates. Begin dates attached dates attached dates attached dates attached da
OTHER: 13. Describe proposed or completed op of starting any proposed work). SE or recompletion. 1. Set CIBP at 3667' Circulate Hole II 2. PUH. to 3300' Spot 60 sx Cmt. 3. PUH. to 2780' Spot 40 sx Cmt. 4. PUH. to 2570' Spot 45 sx Cmt. Works and the start of the beginning of the constructed or closed acts. The Oil Conservation Division Mu 24 hours prior to the beginning of the start of the beginning of the start of	OTHER: Deterations. (Clearly state all pertinent details, EE RULE 1103. For Multiple Completions: Mud Laden Fluid Cap with 35 sx Cmt. OC. & Tag. to Surface. 25 sx. CmT /	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion and give pertinent dates, including estimated date attach wellbore dates and give dates attach dates attached attached dates. Begin date and dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin date dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin dates attached dates. Begin dates attached dates attached dates attached dates attached dates attached dates attached dates. Begin dates attached dates. Begin dates attached dates attached dates attached dates attached da

TO

CURRENT WELLBORE DIAGRAM



2/1/2006 LYN MARR

XTO ENERGY

Well:

Arrowhead Grayburg #337Y

Area:

60' FNL; 1270' FEL Location:

Section 2; T22S; R36E

County:

Lea

WI: 55.59%

NRI:

46.9882%


Spud:

6/19/2001

State:

New Mexico





PREPARED BY: Greg Hicks

DATE: 11/29/05