Submit 3 Copies To Appropriate District Office

District I 1625 N. French Dr., Hobbs, NM 87240 District II
811 South First Artesia NM 87210

State of New Mexico Energy, Minerals and Natural Resources

Form C-	103
Revised March 25,	1999

OIL CONSERVATION DIVISION

30-025-28182 Indicate Type of Lease

WELL API NO.

DO NOT USE THIS PROPOSALS TO BUIL OR TO DEFEND RP JUB BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH FOR PERMIT (FORM C-101) FOR	District III 1000 Rio Brazos Rd., A: District IV 2040 South Pacheco, Sa	ztec, NM 87410	2040 South Pacheco Santa Fe, NM 87505				STATE 🗷 FEE 🗆 6. State Oil & Gas Lease No.				
2. Name of Operator Creveron U.S.A. Inc. 15. Address of Operator 15. Smith Road - Midland, Texas 79705 4. Well Location Office U.B., SEC. 6., F.B. 5.R. 35-E., 565 F.N.L + 24-3 F.E. Unit Letter D : 760 feet from the North line and 484 feet from the West line Section 6 Township 185 Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3998 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ABANDON CHANGE PLANS COMMENCE DRILING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION OTHER COMPLETION CHANGE PLANS OTHER DETAIL Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. THE W/95 jts 2-3/8" proct that 11-25-03 TOH W/sub pump. THE W/csp scrapper to 4381'. THE W/CEBP & CCL., THE W/SO jts 2-7/8" proct that the information above is read of the feet of the state of	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:										
162 163 164			Other				8. Well No	O.			
3. Address of Operator 15 smth Road - Hidland, Texas 79705 4. Well Location BHL: VLB, SEC. 60, FB-5, R-35-E, 565 FNL+3H-5 FEC. Unit Letter D: 760 feet from the North line and 484 feet from the North line and 284 feet from the Nor	1							-			
4 Well Location BHL: ULB, SEC. 6, THS-5, R-35-E, 56.5 FNL + 24-36 FEE Unit Letter D : 760 feet from the North line and 484 feet from the West line Section 6 Township 188 Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 39898 11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS ALTERING CASING COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER CASING OTHER COMPLETION OTHER DOTHER DOTHER COMPLETION CEMENT JOB OTHER: OTHER DOTHER DOTHER CASING SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub parp. TIH w/csg scrapper to 4381'. TIH w/CIBP & CCL. Ask in a set CIBP 1240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/proft tbg. RL 23/9" prod tbg. 11-20-03 Set whipstock 6 75.6 ZA. Mill window f/4225-4235'. Tow 8 4225'. DOW 8 4332'. 12-03-03 TSO w/mills. PU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441', 4455', 5200', 5232'. 12-05-03 Del f/5032-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5579', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner						~~	9. Pool na	me or Wi	ldcat		
Unit Letter D 760 feet from the North line and 484 feet from the Nest line Section 6 Township 185 Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3998 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUG AND ABANDON ABANDONMENT COMMENCE DRILLING OPNS PLUG AND ABANDONMENT COMPLETION OTHER: OTHER COMPLETION OTHER: DRILLING OPNS DILLING OPNS ABANDONMENT CEMENT JOB OTHER: OTHER DRILLING OPNS ABANDONMENT OF SET OF SE	15 Smith Road -	Midland, Texas	79705	/		2851/u	Vacuum Gi	rayburg	San Anc	ires	
Section 6 Township 188 Range 35E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3988' 11. Check Appropriate Box to Indicate, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB OTHER: OTHER: Drill Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. THH w/96 scrapper to 4381'. THH w/CIBP & CCL, and in a set CIBP 240'. THH w/95 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/proft tbg. RU. 140 prod tbg. RD. 12-01-03 MIRU. Tag CIBP @ 4240'. THH w/whipstock. 12-02-03 set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4223'. 12-03-03 TSO w/mills. FU BRA. Drill f/4235-4252', 4283', 4378', 4410', 4440', 94524'. 12-04-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4741', 4757', 4741', 9560', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) I hereby certify that the information above is true and complete to the best of my knowledge and belief: TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355	4. Well Location	3HL: ULB,SE	C.6,T-18-5,R-35+	56	5 FNL	+24 30 .4					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3998' 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: DTILL Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIBP & CCL, and in & set CIBP 1-1240'. TIH w/50 jts 2-7/8" prod tbg. 11-26-03 TIH w/45 stands; circ w/FM & test plug to 500# (good). TOH w/prof2 tbg. RU. 2 prod 350. RD. 12-01-03 MIRU. Tag CIBP @ 4240'. TIH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225'. DOW @ 4322'. 12-03-03 TSO w/mills. FU EHR. Drill f/4235-4252', 4283', 4378', 4410', 4441', 4455', 5400', 5232'. 12-04-03 Drl f/5232-5263', 5295', 5421', 5466', 4694', 4726', 7411', 4757', 4757', 4757', 5500', 5232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5579', 5574', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE	Unit Letter	;				ine and		feet from			ne
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Q ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Drill Horizontal Producer & Complete Other Data 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIBP & CCL, told in & set CIBP 1/4240'. TIH w/50 jts 2-7/8" prod tbg. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/pxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	Section	6							County	y Lea	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT J			The second secon	3	998'						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Drill Horizontal Producer & Complete OTHER Drill Horizontal Producer & Complete OTH	\			dicate	Nature		-				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: DOTHER: Drill Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. THH w/csg scrapper to 4381'. THH w/CIRP & CCL, and in & set CIRP & 1240'. THH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 THH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/proft tbg. FU. 340 prod tbg. RD. 12-01-03 MIRU. Tag CIRP @ 4240'. THH w/mipstock. 12-02-03 Set whitpstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225' 20W @ 4232'. 12-03-03 TS0 w/mills. FU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441', 94524'. 12-04-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4769', 5500', 5232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5587', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist TATLE Regulatory Specialist Title Phone No. 432-687-7355	=						BSEQUEN				
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Drill Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIRP & CCL, and in & set CIRP 1240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 THH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/prod tbg. FU.23/4" prod tbg. FD. 12-01-03 MIRU. Tag CIRP @ 4240'. TIH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225'. ZOW @ 4232'. 12-03-03 TSO w/mills. FU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441, 4524'. 12-04-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4745', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. S1GNATURE TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355	PERFORM REMEDI	AL WORK [_]	PLUG AND ABANDON	ı	REMEDI	AL WORK		X	ALTER	RING CASING	
OTHER: DOTHER: Drill Horizontal Producer & Complete 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIEP & CCL, and in & set CIEP 1240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/prof2 tbg. FU 23/80 prod bdg. RD. 12-01-03 MIRU. Tag CIEP @ 4240'. TIH w/whipstock. 12-02-03 Set whipstock @ 75.6 Za. Mill window f/4225-4235'. TOW @ 4225' 20W @ 4232'. 12-03-03 TSO w/mills. FU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441', 4524'. 12-04-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4745', 5505', 5505', 5505', 55232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5587', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. [See Attached Page 2] Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355	TEMPORARILY ABA	ANDON	CHANGE PLANS								
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIBP & CCL, and in & set CIBP 1/4240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/prof tbg. Pt. 240P prod tbg. RD. 12-01-03 MIRU. Tag CIBP @ 4240'. TIH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225' DOW @ 4232'. 12-03-03 TSO w/mills. PU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441' o/524'. 12-04-03 Drl f/524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4769', 55105', 5115', 5200', 5232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5587', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355	PULL OR ALTER CA	ASING L)				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 'TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIEP & CCL, and in & set CIEP (1240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/prof tbg. Fu 2 3/80 prod tbg. RD. 12-01-03 MIRU. Tag CIEP @ 4240'. TIH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225'. DOW @ 4232'. 12-03-03 TSO w/mills. FU EHA. Drill f/4235-4252', 4283', 4378', 4410', 4441', 4757', 4759', 55105', 5200', 5232'. 12-05-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4759', 5105', 5200', 5232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5587', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. (See Attached Page 2) Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355	OTHER:				OTHER:	Drill Ho	rizontal P	roduœr	& Comp.	lete	X
12-01-03 MIRU. Tag CIBP @ 4240'. TTH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225' BOW @ 4232'. 12-03-03 TSO w/mills. PU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441	of starting any	proposed work).	SEE RULE 1103. For M	Aultiple	Completi	ons: Attacl	n wellbore di	agram of	propose	d completion	
12-01-03 MIRU. Tag CIBP @ 4240'. TTH w/whipstock. 12-02-03 Set whipstock @ 75.6 ZA. Mill window f/4225-4235'. TOW @ 4225' BOW @ 4232'. 12-03-03 TSO w/mills. PU BHA. Drill f/4235-4252', 4283', 4378', 4410', 4441	11-24-03 MIRU. TIH w/96 jts 2-3/8" prod tbg. 11-25-03 TOH w/sub pump. TIH w/csg scrapper to 4381'. TIH w/CIBP & CCL, weld in & set CIBP 1240'. TIH w/50 jts 2-7/8" prod tbg to 1570'. 11-26-03 TIH w/45 stands; circ w/FW & test plug to 500# (good). TOH w/prof tbg. Pu 2-3/8" prod tbg. RD.										
12-04-03 Drl f/4524-4568', 4578', 4631', 4646', 4694', 4726', 4741', 4757', 4757', 52105', 52105', 52105', 5220', 5232'. 12-05-03 Drl f/5232-5263', 5295', 5421', 5426', 5485', 5497', 5579', 5587', 5674', 5680', 5742'. TOH, motor failure. Drl f/5742-5750', 5831', 5843', 5862'. [See Attached Page 2] Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Telephone No. 432-687-7355	12-01-03 MI 12-02-03 Se	IRU. Tag CIBP et whipstock @	0 4240'. TIH w/whi 75.6 ZA. Mill wind	pstock ow f/4	225–4235	'. TOW @	4225 280	w @ 4232	Google	128.39 28.39 20.59	
motor failure. Drl f/5742-5750', 5831', 5843', 5862'. [See Attached Page 2] I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Telephone No. 432-687-7355			, 4578', 4631', 464	6', 46	94', 472	6', 4741'	, 4757', à	169 27 PE	951 - 3	1/15', 5200',	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355							, 5587', 5	674', 56	80', 5'	742'. TOH,	
SIGNATURE Skinner TITLE Regulatory Specialist DATE 12-31-03 Type or print name Laura Skinner Telephone No. 432-687-7355							(S	ee Attac	hed Pag	gne 2)	
Type or print name Laura Skinner Telephone No. 432-687-7355	I hereby certify that the	information above i	s true and complete to the	best of	my knowle	dge and belie	ef.				
The state of the s	SIGNATURE	jaura Ski	inner	TITL	E Regula	atory Spec	cialist	D	ATE	12-31-03	
APPROVED BY Conditions of approval, if any: TITLE PETROLEUM ENGINEER DATE FEB 2 3 2004	Type or print name 1	Laura Skinner					,		ie No.	4 32-687 - 735	5_
APPROVED BY	(This space for State use)										
		ral, if any:	May .	TIT	LE	ETROLEU	M ENGINEE	DA	TE F E	B 2 3 2004	F

CENTRAL VACUUM UNIT NO. 162 PAGE 2

- 12-06-03 Drl f/5862-5989', 6009', 6021', 6094', 6115', 6151', 6193', 6205', 6241', 6263', 6304', 6315', 636
- 12-07-03 Drl f/6367-6488', 6557', 6579', 6620', 6683', 6697', 6746', 6760', 6841', 6850', 6906' **TD**.
- 12-08-03 Short trip to KOP. Circ. TOH, lay down DP. TIH. Set RBP @ 4125' and test to 750 psi. LDDP. Rig Down.
- 12-10-03 MIRU. TIH w/Baker retrieving head & PU 131 jts 3-1/2" tbg to 4103'.
- 12-11-03 Rel RBP; TOH w/132 jts 3-1/2" tbg & lay down RBP. TIH w/2-7/8" tbg to 2814' & 3-1/2" tbg; tagged @ 6906'. TOH w/3-1/2" tbg; bit @ 2825'.
- 12-12-03 TOH w/ 2-7/8" tbg & bit. TIH w/11 ported subs, 2-7/8" tbg, pkr, SN, 3-1/2" tbg; set pkr @ 4106' (bottom sub @ 6885'). Load & test csg to 500# (good).
- 12-15-03 Acidize Grayburg San Andres OH lateral from 4225' to 6906' w/66,000 gals 20% HCL acid.
- 12-16-03 Open well to frac tank. Flowed back 8 hrs & recovered 600 bbls. MI to pump chemical squeeze.
- 12-17-03 MI w/new 2-7/8" prod tbg & move out work string. (Rel pkr.) TIH w/BHA. Rig down. Installed QCI hanger.
- 12-18-03 Hook up well head & flow line. Test run unit for 30 min. SD. Rig down. FINAL REPORT.