



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Jim Noel

Cabinet Secretary

Karen W. Garcia

Deputy Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

24-Nov-10

RANGER 40 PETROLEUM, LLC

1004 COLLIER CENTER WAY #206

NAPLES FL 34110-

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

LANGLIE JAL UNIT No.026			30-025-11322-00-00	
Active Injection - (All Types)			M-32-24S-37E	
Test Date:	11/23/2010	Permitted Injection PSI:	Actual PSI:	
Test Reason:	5-year Test	Test Result: F	Repair Due:	2/26/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Casing	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure. 2 attempts to pressure annulus were unsuccessful.			
LANGLIE JAL UNIT No.019			30-025-11323-00-00	
Active Injection - (All Types)			L-32-24S-37E	
Test Date:	11/23/2010	Permitted Injection PSI:	Actual PSI:	
Test Reason:	5-year Test	Test Result: F	Repair Due:	2/26/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Casing	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure. 6 attempts to pressure annulus were unsuccessful.			
LANGLIE JAL UNIT No.039			30-025-11442-00-00	
Active Injection - (All Types)			D-4-25S-37E	
Test Date:	11/23/2010	Permitted Injection PSI:	Actual PSI:	
Test Reason:	5-year Test	Test Result: F	Repair Due:	2/26/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Casing	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure. Made 6 attempts made to pressure up on annulus.			

LANGLIE JAL UNIT No.024**30-025-24479-00-00**

O-32-24S-37E

Active Injection - (All Types)

Test Date:	11/23/2010	Permitted Injection PSI:	Actual PSI:
Test Reason:	5-year Test	Test Result:	F
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Casing
Comments on MIT:	Well will not hold pressure. 5 attempts made to pressure up on annulus.		

LANGLIE JAL UNIT No.008**30-025-24839-00-00**


G-32-24S-37E

Active Injection - (All Types)

Test Date:	11/23/2010	Permitted Injection PSI:	Actual PSI:
Test Reason:	5-year Test	Test Result:	F
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Casing
Comments on MIT:	Well will not hold pressure. Several attempts to pressure annulus unsuccessful.		

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

RANGER 40 PETROLEUM, LLC
1004 COLLIER CENTER WAY #206
NAPLES, FL 34110



HASLER
015H14150977
\$0.44
11/24/10
Mailed From 88240
US POSTAGE