

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26053
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	MARK OWEN
8. Well No.	8
9. Pool Name or Wildcat	PENROSE SKELLY GRAYBURG
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3394' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>P</u> : <u>900'</u> Feet From The <u>SOUTH</u> Line and <u>660'</u> Feet From The <u>EAST</u> Line Section <u>34</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3394' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ PLUGBACK TO GRAYBURG

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-06-03: MIRU KEY #284.
11-07-03: REL TAC. TIH TO 2175'.
11-10-03: PU CIBP & TIH TO 7150'. SET CIBP. LD 40 JTS TBG.
11-11-03: TOH W/SETTING TOOL. PU CIBP & TIH. RUN CBL-LOGGING TOOL.
11-12-03: RUN CBL FR 5000-2400. PERF @ 3651-57, 3670-76, 3700-06, 3720-24, 3729-35, 3746-52, 3756-62, 3773-77, 3784-88, 3799-3803.
PU PPI PKR & TIH TO 3600.
11-13-03: ACIDIZE W/PPI PKR. ACIDIZE W/2000 GALS 15% HCL. FLOWING.
11-14-03: PU FRAC PKR & SET @ 3533'.
11-15-03: FRAC PERFS W/66,000 GALS YF135 & 138,000# 16/30 SAND & 3000# RESIN COATED 16/30 SAND.
11-17-03: SWABBING.
11-18-03: RUN GR/CCL AFTER FRAC PRISM LOG FR 4100-3300. RU SWAB. 7 HR TEST.
11-19-03: REL FRAC PKR. LD WS & PKR. CHANGE OVER TO 2 7/8". TIH W/WS.
11-20-03: RUN SUB PUMP & 2 7/8" TBG. RIG DOWN. TURN WELL OVER TO PRODUCTION TO HOOK UP FLOWLINE & START UP SUB PUMP.

FINAL REPORT

1-09-04: ON 24 HR OPT. PUMPING 25 OIL, 353 GAS, & 1400 WATER



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 1/13/2004
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED Paul F. Nichols TITLE PETROLEUM ENGINEER
CONDITIONS OF APPROVAL, IF ANY:

DATE FEB 23 2004
DeSoto/Nichols 12-93 ver 1.0

2A Wantz Granite Wash