State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL C	ONSERVATION DIVISION	Keviscu 5-27-2004
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-37105
DISTRICT II DEC 1 A 7010		5. Indicate Type of Lease
DISTRICT II 1301 W. Grand Ave, Artesia, NM 8821DEC 1 4 2010		STATE X FEE V
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 874 HOBBSOCD		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		North Hobbs (G/SA) Unit Section 25
1. Type of Well: Oil Well X Gas Well	Other	8. Well No. 642
2. Name of Operator		9. OGRID No. 157984
Occidental Permian Ltd.		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	/	10. Pool name or Wildcat Hobbs (G/SA) V
4. Well Location	ر کھر	
Unit Letter I : 1645 Feet From The		et From The East Line
Section 25 Township	18-S Range 34-	E NMPM Lea County
11. Elevation (Show 3657' GL	whether DF, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure	[]	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
	Volume bbls; Construction M	
	volume bbis, construction m	actia
12. Check Appropriate Box to NOTICE OF INTENTION TO:	o Indicate Nature of Notice, Report, or SUB	Other Data SEQUENT REPORT OF:
		ALTERING CASING
	COMMENCE DRILLING OF	PNS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion	CASING TEST AND CEMEI	
OTHER:	OTHER: Clean out/Per	rforate/Acid Treat
 Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Complet RUPU & RU. NU BOP/ND wellhead. POOH w/ESP equipment. RIH w/bit. Tag @4279'. RU power swivel & stripper 1 	ions: Attach wellbore diagram of proposed RUPU 11/22/2010	completion or recompletion. RDPU 11/29/2010
well clean. RD power swivel & stripper head. POOH w/bi		
 5. RU pump truck & pump 40 bbl of Xylene down tubing. 6. RU wireline & perf tubing @4338-47', 4325-27', 4319- 		10# to remove Xylene from well bore & tbg.
7. RIH w/SPA packer. RU HES & perform straddle acid jo	bb w/2950 gal of 15% PAD acid. Flush v	v/15 bbl of 10#. RD HES.
8. Perform scale squeeze w/100 bbl of fresh water & 200 g		
 9. RIH w/ESP equipment set on 126 jts of 2-7/8" tubing. 10. ND BOP/NU wellhead. 11. RDPU & RU. Clean loca 		
I hereby certify that the information above is true and complete to the t	pest of my knowledge and belief. I further certify	that any pit or below-grade tank has been/will be
constructed or closed according to NMOCD guidelines, a general p	permit or an (attached) alternativ	e OCD-approved
man a hard	plan	
SIGNATURE INCHANGE	TITLE Administrative	Associate DATE 12/10/2010
	ail address: <u>mendy_johnson@oxy.com</u>	TELEPHONE NO. 806-592-6280
For State Use Only	JETRAL EUR	A ENGINEER DEC 1 6 2010
APPROVED BY		A ENGINEED DEC 1 6 2010
CONDITIONS OF APPROVAL IF ANY:	TITLE	DATE