State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OF CONSERVATION DIVISION	
DISTRICT I 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	WELL API NO. 30-025-28980
DISTRICT III 1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III HOBBSOCD	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III HOBBSOOD	6. State Oil & Gas Lease No.
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS	
	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	South Hobbs (G/SA) Unit
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 183
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location Unit Letter E: 2540 Feet From The North 1423 Fe	et From The West Line
Section 5 Township 19-S Range 38-	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3622' GL	E Man Eca County
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	PNS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Kill well. POOH w/ESP equipment.	
2. Clean out to TD @4313'.	
3. Acid treat well w/2500 gal of 15% NEFE acid.	
4. Perform scale squeeze.	
5. Run back in hole w/ESP equipment.6. Return well to production.	
o. Return wen to production.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be	
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ve OCD-approved
SIGNATURE MUNICIPALITY SIGNATURE Administrative	Associate DATE 01/17/2011
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com	
For State Use Only	
Tor State Ose Only	
APPROVED BY TITLE PETROLEU	M ENGINEER DATE JAN 2 0 2011