Office	^{3 Copies To} Appropriate District State of New Mexico <u>1</u> Energy, Minerals and Natural Resources					Form C-103 June 19, 2008
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM SECENCE District II 1301 W. Grand Ave., Artesia, NM 88210 District III FFR 1 1 2011 1220 South St. Francis Dr.					WELL API	
District II 1301 W. Grand Ave., Artesia NM 88210 OIE CONSERVATION DIVISION						30-025-09968
District III 1000 Rio Brazos Rd., Aztec, NM 87470 11 2011 1220 South St. Francis Dr.					5. Indicate Type of Lease STATE X FEE 🖾 🦟	
Santa Fe NIM 87505					6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa FeinoBBSOCD 87505						
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Na	ame or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)					Paddock Unit	
1. Type of Well: Oil Well Gas Well Other					8. Well Number 17	
2. Name of Operator John H. Hendrix Corporation					9. OGRID Number 012024	
3. Address of Operator					10. Pool name or Wildcat	
P. O. Box 3040, Midland, TX 79702-3040					Paddock	
4. Well Location						
Unit Letter <u>E</u> : 1980 feet from the North line and 660 feet from the West line						
Sectio	on 2	Township		Range 37E	NMPM	Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3368' GR						Arra and a state
		3308 0	K		- -	
	12 Check Ar	propriate Box to	Indicate N	ature of Notice	Deport or (than Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL						
TEMPORARILY ABANDON L CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT						PANDA 🗌
			_			
OTHER: 13. Descrit	be proposed or comple	ted operations (Cle	arly state all r	OTHER:	l give portinor	at datas including setimated data
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
Dec 6-13	POOH w/ prod aqui	mont CILL alaan	autiumle and f			A
Dec 6-13POOH w/ prod equipment. GIH, clean out junk and fill to 5045'; drill out CIBP @ 5044'.Dec 14-15Clean out hole to 5200'. Try to set new CIBP @ 5160' but would not set. Fill hole w sand to 5149'.						
Dec 15 Acidize perfs w/ 1500 gal 15% nefe HCl. SD. Wait on Frac						
Dec 27 Frac well f/5011-5149' w/ 100,000# sand in 55200 gal x-link gel. AIR = 31bpm; Pavg = 3817#, 15 min SIP = 1681#						
Jan 3-11Clean out hard fill f/5013-5160'. Circ hole clean.Jan 12GIH w/ prod equipment. EOT @ 5102'. PBTD @ 5160'. Test well.						
Feb 1 Test: 21 bbls oil, 30 bbls water, 20 MCF.						
Spud Date:		R	ig Release Da	te:		
	- <u>1</u>			L		J
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE & D //						
SIGNATURE	urg-pen	- ltayn	HTLE En	gineer DA	TE 02/10/1	<u></u> .
Type or print nat	me <u>Carolyn Dora</u>	n Haynes	E-mail addre	ss: cdoranhaynes(Wibbe are	PHONE: 122 601 6621
For State Use C					wjinic.org	PHONE <u>: 432-684-6631</u>
	, Ash		PET	ROLEUM ENGIN	Ebh	FEB 1 5 2011
APPROVED BY:						

I

× `,