Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-10. June 19, 200
District I 1625 N. French Dr., Hobbs, NM 87240 ECEIVED	WELL API NO.
District.II 1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVISION 1 2 201220 South St. Francis Dr.	<u>30-025-39694</u>
District III District III	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV HOBBSOCD Santa Fe, NM 87505	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: North Vacuum ABO unit
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 308H
2. Name of Operator	9. OGRID Number
XTO Energy, Inc.	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. Loraine, Ste. 800 Midland, TX 79701 4. Well Location	Vacuum: ABO, North
Unit Letter P : 380 feet from the South line and	350 feet from the East lin
Section 26 Township 17S Range 34E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, 4 4010' GL	etc.)
12. Check Appropriate Box to Indicate Nature of Notice,	, Report, or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE	ALTERING CASING [LING OPNS. 🗌 P AND A [JOB 🗍
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	ALTERING CASING [LING OPNS. JOB <u>1 Completion</u>
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE COMPL OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac	ALTERING CASING [LING OPNS. P AND A JOB I 1 Completion I give pertinent dates, including estimated date I ch wellbore diagram of proposed completion I 11.6# P110 LT&C csg 9', 3', 20' of 4-1/2" 11.6# P110 , latched onto liner hanger @
 PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT POWNHOLE COMMINGLE OTHER: OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. 6/14/10 - MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 1 6/15/10 - RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550psig, RD 	ALTERING CASING [LING OPNS. P AND A JOB I 1 Completion I give pertinent dates, including estimated date I ch wellbore diagram of proposed completion I 11.6# P110 LT&C csg 9', 3', 20' of 4-1/2" 11.6# P110 , latched onto liner hanger @
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT POWNHOLE COMMINGLE OTHER: OTHER: New Well OTHER: OTHER: New Well OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 6/14/10 - MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 1 6/15/10 - RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550psig, RD 6/18/10 - tested lines to 8200psig, no show of pumping out plug, load	ALTERING CASING [LING OPNS. P AND A JOB I 1 Completion I give pertinent dates, including estimated date I ch wellbore diagram of proposed completion I 11.6# P110 LT&C csg 9', 3', 20' of 4-1/2" 11.6# P110 , latched onto liner hanger @
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OWNHOLE COMMINGLE OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. 6/14/10 - MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 1 6/15/10 - RIH w/seal assy, xover, 210jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550psig, RD 6/18/10 - tested lines to 8200psig, no show of pumping out plug, loa CONT'D ON NEXT PAGE	ALTERING CASING [LING OPNS. P AND A [JOB 1 Completion [give pertinent dates, including estimated date ch wellbore diagram of proposed completion 11.6# P110 LT&C csg & 9', 3', 20' of 4-1/2" 11.6# P110 , latched onto liner hanger @ aded hole w/42bbls
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PULD OR ARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT POWNHOLE COMMINGLE OTHER: OTHER: New Well OTHER: OTHER: New Well OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 6/14/10 - MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 1 6/15/10 - RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550psig, RD 6/18/10 - tested lines to 8200psig, no show of pumping out plug, loa CONT'D ON NEXT PAGE Spud Date: Rig Release Date: hereby certify that the information above is true and complete to the best of my knowled	ALTERING CASING [LLING OPNS. P AND A JOB I 1 Completion I give pertinent dates, including estimated date I ch wellbore diagram of proposed completion I 11.6# P110 LT&C csg 9', 3', 20' of 4-1/2" 11.6# P110 , latched onto liner hanger @ aded hole w/42bbls lge and belief.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT POWNHOLE COMMINGLE OTHER: New Well OTHER: OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. 6/14/10 MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 11 6/15/10 RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550 psig, RD 6/18/10 tested lines to 8200 psig, no show of pumping out plug, loat CONT'D ON NEXT PAGE Spud Date: Rig Release Date: hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE REMEDIAL WURAN TITLE Regulate reg	ALTERING CASING [LLING OPNS. P AND A JOB PAND A 1 Completion [give pertinent dates, including estimated date [ch wellbore diagram of proposed completion [11.6# P110 LT&C csg [§ 9', 3', 20' of 4-1/2" 11.6# P110 [, latched onto liner hanger @ [aded hole w/42bbls [lge and belief. [ory Analyst DATE 1/6/11 toenergy.com [
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: New Well CASING/CEMENT DOTHER: OTHER: New Well CASING/CEMENT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. 6/14/10 - MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 11 6/15/10 - RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr. 9372', L&T TCA to 550psig, RD 6/18/10 - tested lines to 8200psig, no show of pumping out plug, load CONT'D ON NEXT PAGE Spud Date: Rig Release Date: Rig Release Date: Rig Release Date: Preby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE Regulaty TITLE Regulaty Ype or print name Patty Urias E-mail address;	ALTERING CASING [LING OPNS. P AND A JOB PAND A 1 Completion [] give pertinent dates, including estimated date [] ch wellbore diagram of proposed completion [] 11.6# P110 LT&C csg [] & 9', 3', 20' of 4-1/2" 11.6# P110 [] , latched onto liner hanger @ [] aded hole w/42bbls [] lge and belief. [] ory Analyst DATE 1/6/11 toenergy.com PHONE 432-620-4318
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT POWNHOLE COMMINGLE OTHER: New Well OTHER: OTHER: New Well 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. 6/14/10 MIRU PU, ND WH & NU BOP, RIH w/seal assy, xover & 4-1/2" 11 6/15/10 RIH w/seal assy, xover, 210 jts 4-1/2" 11.6 P110 LT&C csg & LT&C csg subs, RU pmp truck, brk circ w/93bbls 2% kcl wtr, 9372', L&T TCA to 550 psig, RD 6/18/10 tested lines to 8200 psig, no show of pumping out plug, loat CONT'D ON NEXT PAGE Spud Date: Rig Release Date: hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE REMEDIAL WURAN TITLE Regulate reg	ALTERING CASING [LING OPNS. P AND A JOB PAND A 1 Completion [] give pertinent dates, including estimated date [] ch wellbore diagram of proposed completion [] 11.6# P110 LT&C csg [] & 9', 3', 20' of 4-1/2" 11.6# P110 [] , latched onto liner hanger @ [] aded hole w/42bbls [] lge and belief. [] ory Analyst DATE 1/6/11 toenergy.com PHONE 432-620-4318

North Vacuum ABO Unit #308H C-103 cont'd

- 6/24/10 RU frac truck & pmp truck, L&T TCA w/1BW to 500psig, well communication w/ backside, RD frac equip, ND frac valve, RU PU machine
- 6/25/10 RU vac truck, ND frac valve, RU csg crew & LD machine, rel seal assy, POOH w/tbg & seal assy – seal assy latch was broken, left fingers & mule tail in well, RD
- 6/26/10 RIH w/4' magnet & 2-7/8" L80 tbg, work into liner hanger & tag fish @ 9382', POOH w/ tbg & LD magnet, did not recover any metal, PU, RIH w/tbg spear dressed w/3.681" grapple & 2-7/8"tbg, tag fish @ 9382', rotate & work tool into fish, pull 40K over string weight, unable to work fee, rel grapple & POOH
- 6/27/10 RIH w/open ended 2-7/8" L80tbg, work into seal assy @ 9362', PUH out of assy, prep to run down hole camera
- 6/28/10 RU WL & expro, RIH w/downhole camera, RU pump truck & vac truck, circ well w/ clean wtr, pump camera down & run across parted latch assy & thru 4-1/8" muleshoe guide sub, found parted latch assy, set in latch receiver, POOH and RD
- 7/02/10 Frac ABO lateral fr 9896-13292' thru stim sleeves in 96 stgs w/235138gls 15% ZCA, 186414gls 20% CCA, 177961gls R11 18# gel wtr & 269637gls slick wtr, RD
- 705/10 ND frac valve, NU BOP, MI & rack 210jts 4-1/2" 11.6# P110, RU csg crew & RIH w/seal assy & 209jts 4-1/2" P110, work seal assy into smooth bore receptacle, PU 38' of 4-1/2" subs, space out & land w/57pts compression
- 7/06/10 ND BOP & NU spool, NU BOP, RU pmp trk, L&T TCA w/1BFW to 1000psig, MIRU CT unit, Std RIH w/3-1/2" OD magnet, 2" CT, while circ well wFW
- 7/07/10 RIH w/magnet, tag @ 9377' POOH w/4 pieces of latch assy,
- 7/10/10 RIH w/CT & magnet, tag @ 9377', POOH w/2 pieces of latch assy, POOH w/CT & magnet. RIH w/ 3-5/8" bit, motor & 2"CT, DO stim sleeves @ 9671', 9616', 10165', POOH
- 7/11/10 RIH w/3-5/8" bit, 2"CT & motor, DO sleeves @ 10414', 10650', 10892, PUH w/bit to 9300' & circ btm up, DO sleeves @ 11140', 11376', PUH w/bit to 9300' & circ btm up, DO sleeves @ 11592', 11834', 12071', 12312', 12557', 12805', 13053' & tag @ 13290', circ btm up, POOH & RD
- 7/13/10 RU vac trk, POOH w/tbg and seal assy, ND BOP & ND 10K WH, NU 5K WH & BOP w/2-7/8" tbg rams, RD
- 7/14/10 RU spooler, RUH w/SMG sensor, TR5 120/2165/22 UT mtrs, seal/intake, 2 TD850 pmps, 211/105 stgs, 2-7/8" x 4' J55 tbg sub, 2-7/8" SN, 252jts of 2-7/8" 6.5# J55EUE 8rd prod tbg, RD, ND BOP & NU WH, 70'mtr lead #6 cable, 8200' #4 flat cable, PI @ 8148', sensor @ 8189', RDMO PU