State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

| FILE IN TRIPLICATE RECEIVED CONSERVATION DIVISION | | |
|---|---|--|
| DISTRICT I 1220 South St. Francis Dr | WELL API NO. | |
| 1625 N. French Dr., Hobbs, NM 88240 MAR 0 3 2011 Santa Fe, NM 87505 | 30-025-34372 5. Indicate Type of Lease | |
| DISTRICT II 1301 W. Grand Ave, Artesia, NM 88219 AOBBSUCD DISTRICT III | STATE X FEE | |
| DISTRICT III | 6. State Oil & Gas Lease No. | |
| 1000 Rio Brazos Rd, Aztec, NM 87410 | | |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | North Hobbs (G/SA) Unit | |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 1. Type of Well: | Section 33 8. Well No. 523 | |
| Oil Well X Gas Well Other | 8. Well No. 523 | |
| 2. Name of Operator | 9. OGRID No. 157984 | |
| Occidental Permian Ltd. 3. Address of Operator | 10. Pool name or Wildcat Hobbs (G/SA) | |
| HCR 1 Box 90 Denver City, TX 79323 | 13555 (5.5.1) | |
| 4. Well Location | | |
| Unit Letter F : 2000 Feet From The North 2450 Feet | t From The West Line | |
| Section 33 Township 18-S Range 38-E | NMPM Lea County | |
| 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3642' GL | | |
| Pit or Below-grade Tank Application or Closure | | |
| Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water | | |
| Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material | | |
| | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN | NS. PLUG & ABANDONMENT | |
| PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN | T JOB | |
| OTHER: Clean out/Acidize X OTHER: | | |
| 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any | | |
| proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | |
| 1. Kill well. | | |
| 2. POOH w/ESP equipment. | | |
| 3. Clean out to TD @4350'. | | |
| 4. Acid treat well w/3500 gal of 15% PAD acid.5. Perform scale squeeze. | | |
| 6. Run back in hole w/ESP equipment. | | |
| 7. Return well to production. | | |
| | | |
| | | |
| | | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or | | |
| closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved | | |
| I - I - I I I | SIGNATURE OF A MACHINE AND THE STATE OF THE | |
| SIGNATURE Plan SIGNATURE Administrative | Associate DATE 03/02/2011 | |
| SIGNATURE MINGLE Administrative A | | |
| | Associate DATE 03/02/2011 TELEPHONE NO. 806-592-6280 | |
| SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com For State Use Only | 03/02/2011 | |