

State of New Mexico  
Energy, Minerals and Natural Resources

RECEIVED

MAR 07 2011

HOBBSD

## OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. /

30-025-33033

5. Indicate Type of Lease

STATE ☐ FEE ☒ X

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

Maljamar Grayburg Unit

8. Well Number 86

9. OGRID Number 270265

10. Pool name or Wildcat

Maljamar; Grayburg-San Andres

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒

2. Name of Operator

SandRidge E&amp;P, LLC

3. Address of Operator

123 Robert S. Kerr Ave, OKC OK 73102-6406

4. Well Location

Unit Letter F : 2537 feet from the N line and 2603 feet from the W lineSection 4 Township 17S Range 32E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

4093 GR

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐DOWNHOLE COMMINGLE ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☒ XCASING/CEMENT JOB ☐OTHER: ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2-24-11 MI RU plugging equipment. POH &amp; LD rods &amp; pmp. Dig out cellar and NU BOP.

2-25-11 Pld tbg. RIH &amp; set CIBP @ 3850'. Circulate 9.5# mud w/89 bbls. Spot 25 sx class C cmt on CIBP. Pull up &amp; WOC. Tgd cmt @ 3600'. Pld up to 3347' and spot 25 sx Class C cmt. Pld out of cement &amp; WOC.

2-28-11 RIH and tag plug @ 3126'. Pull tbg to 2722'. Load hole. Spot 25 sx Class C. Pld out of cement. WOC. Tag @ 2533'. Pull up to 2397'. Spot 40 sx Class C (Combine plugs 4 &amp; 5). Pull out of cement. WOC. Tag plug @ 2009'. Pull tbg to 1245'. Spot 35 sx Class C. POH w/tbg. Close BOP.

3-1-11 Ran tbg to tag plug. Tagged @ 900'. LD tbg. ND BOP. Ran 2 jts tbg. Circ cement to surface with 10 sx Class C. Pld &amp; LD tbg. RD. Move out.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OGD Web Page under  
Forms, www.emnrd.state.nm.us/ocd.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Regulatory Manager

DATE 03/02/2011

Type or print name Linda Guthrie E-mail address: lguthrie@sandridgeenergy.com PHONE: 405-429-6085

## For State Use Only

APPROVED BY:

TITLE

Staff MGR

DATE 3-8-2011

Conditions of Approval (if any):

COK