At a second s	
Submit 3 Copies To Appropriate District State of New Mexico Office CEIVEnergy, Minerals and Natural Resources District I	Form C-103
District I	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240 District II 1301 W. Grand Ave., Artesia MAR 88210 1301 W. Grand Ave., Artesia MAR 88210 1220 South St. Francis Dr.	30-025-07794
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztea, NBBSOCD District IV 1000 Rio Brazos Rd., Aztea, NBBSOCD District IV 1000 Rio Brazos Rd., Aztea, NBBSOCD District IV 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Warren McKee Unit
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250	10. Pool name or Wildcat /
4. Well Location	
Unit Letter <u>G</u> : <u>1980</u> feet from the <u>north</u> line and <u>1880</u> feet from the <u>east</u> line	
Section 18 Township 20S Range 38E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3553'	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	NG OPNS. PLUG AND X ABANDONMENT
PULL OR ALTER CASING DULTIPLE CASING TEST AND CEMENT JOB	
OTHER: OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
Liabiti COA which	ved for purgging of well bore only. tv under bolid is retained pending receipt 03 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.courd.state.nm.us/ocd.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed accrifting to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan	
	tory Analyst DATE 3(1(1
Type or print name David Stewart E-mail address:	david_stewart@oxy.com Telephone No. 432–685–5717
For State Use Only	
APPROVED BY Complement TITLE State 1	MED DATE 3-9-2011
Conditions of Approval, if any:	
	r -

,

WMU #110

- Date Remarks
- 2/15/11 Clear Loc, MIRU PU, NDWH, NUBOP
- 2/16/11 PU & RIH w/ 4-3/4 bit, bit sub and 2-7/8, tag @ 5385'. RU pwr swivel, drill cmt @ 5385', tag CR @ 5402', circ well clean
- 2/17/11 DO CR to 5405', DO to 5697', POOH, RD PS, RIH & tag @ 9010', circ hole clean, PUH.
- 2/18/11 POOH w/ tbg, LD BHA, RIH w/ tbg, NDBOP, NUWH, RDPU, WO P&A rig
- 2/19/11 MIRU P&A, NDWH, NUBOP, RIH & tag @ 9010', circ w/ 100 bbls 10# MLF, spot 25sx Cl H cmt, Calc TOC-8779', PUH.
- 2/20/11 PUH & set tbg @ 7030', could not pump into tbg, plugged
- 2/21/11 RIH w/ WL, RIH & perf @ 6145', POOH, LD 25 bad jts, RIH w/ tbg back to 8044'
- 2/22/11 RIH w/ tbg, SD for rig repairs. Try to circ, well would pressure up after 20bbl, RIH w/ WL & tag plug@ 8990', LD 1 jt, try to pull loose.
- 2/23/11 RIH w/ WL & tag bot of tbg @ 8990', Perf 8 shots, POOH w/ WL, EIR & spot 25sx Cl H cmt @ 8990', Calc TOC 8740'. PUH & spot 25sx Cl H cmt @ 7009', calc TOC 6788'. PUH & spot 25sx CL H cmt, Calc TOC-6160', PUH w/ tbg.
- 2/24/11 POOH w/ tbg, SD high winds
- 2/25/11 RIH w/ pkr & set pkr @ 5800'. RIH w/ WL & perf @ 5900', EIR & sqz 45sx Cl C cmt, Rel pkr & PUH, pkr got stuck, POOH without pkr.
- 2/26/11 RIH & tag pkr @ 5504', called NMOCD, rec OK to spot plug on pkr. Spot 90sx CI C cmt @ 5504', POOH & WOC. RIH w/ pkr & set @ 3293', RIH w/ WL & tag cmt @ 4630', PUH & perf @ 3758', EIR & sqz 45sx CL C cmt, , PUH, WOC.
- 2/28/11 RIH & tag cmt @ 3380', PUH & set pkr @ 2216'. RIH w/ WL & perf @ 2700', POOH w/ WL, EIR & sqz 45sx CI C cmt, PUH, WOC. RIH & tag cmt @ 2591', PUH & perf @ 1550', RIH & set pkr @ 1146', EIR & sqz 45 sx CL C cmt, PUH, WOC.
- 3/1/11 POOH & LD 36 jts, ND BOP, RU WL & Lubr, RIH & tag cmt @ 1420', PUH & perf 5-1/2" & 8-5-8" csg @ 345'. EIR w/ full returns, sqz 250sx CL C cmt, circ cmt to surf. RD P&A unit.