-Rom 31605. WED (April 2004)	UNITED STATE: DEPARTMENT OF THE	5	HOBRS	1	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
a 01111				5. Lease Ser	rial No.
ADRSU COUNDAT	' NOTICES AND REI	PORTS ON W	VELLS e-enter an		3965 - 032715 n, Allottee or Tribe Name
abandoned w	vell. Use Form 3160-3 (/	APD) for such	proposals.		
1 Type of Well	NPLICATE- Other inst	ructions on rev	/erse side.		or CA/Agreement, Name and/or No.
	Gas Well				ame and No. er Jal Unit #402
2. Name of Operator Resaca Oper	rating Company			9. API W	Vell No.
3a Address 1331 Lamar, Suite 1450 Ho	uston, TX 77010	3b. Phone No. (inc. 432-580-8500	lude area code)		5-32292 S /
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)	•	·····		t;T-Y-7R/Langlie Mattix;7R-Q-G
2150' FSL & 50' FWL Sec. 19, T24S, R37E	(II. County Lea, N	or Parish, State
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE, I	REPORT, O	R OTHER DATA
TYPE OF SUBMISSION]	TYPE OF ACTION		·
Notice of Intent	Acidize	Deepen Fracture Treat	Production (St	art/Resume)	Water Shut-Off
Subsequent Report	Casing Repair	New Construction		handan	Other Clean Out and Stimulate Perfs w/
Final Abandonment Notice	Convert to Injection	Plug and Abando Plug Back	Water Disposal	+	Foam Frac
 2.) RIH w/ 4 ¼" Bit and di 3.) Clean out to 3750' TD. 4.) RU Service Company 4 5.) Foam Sand Frac Perfs plus 1.71 MMCF Nitroger 6.) RD Service Company. production until pressure 7.) POOH w/ 2 7/8" work 8.) RIH w/ 2 7/8" tubing. 9.) RDMO Pulling Unit, cl 	d Above Ground Steel Pit; NU rill collars on 2 7/8" work strin & prep to fracture stimulate w 3006'-3658' w/ approximately 1 diverting with 130 Bio Ball So Install adjustable choke manif depletes. string and lay down packer; cl RIH w/ pump and rods. lean location. clean and dispose	ig. ell down work strin 105,000# 16/30 Bra alers. old w/ pressure gau ean out frac sand d e of pit fluids.	g. Idy Brown Sand & 105 Ige. Flow back well & o own to 3750' TD.	clean up well,	esin coated Brady Brown Sand; monitoring pressure and sand lugge - lott et
14. I hereby certify that the fore			· · · ·		-
Name (Printed/Typed) Melanie Reyes		Title	Engineer Assistant		
Signature	f-	Date	. (03/03/2011	
	THIS SPACE FOR F	EDERAL OR	STATE OFFICE	USE	<u></u>
Approved by Conditions of approval, if any, are a certify that the applicant holds legal which would guittle the applicant to	attached. Approval of this notice of or equitable title to those rights in	loes not warrant or the subject lease	Title SS (S Office CAD	I	Date 3-13-1(
	e 43 U.S.C. Section 1212, make it a	crime for any person is to any matter within	knowingly and willfully	to make to any	y department or agency of the United
(Instructions on page 2)		-		17	VPETROLEUM ENGINEE
	· · · ·		• •	K	MAR 2 1 2011

÷

	PLETION SCHEMATIC	LEASE NAME Cooper Jal Unit WELL NO. 402
		STATUS: Active Oil API# 30-025-32292
		LOCATION: 2150 FSL & 50 FWL, Sec 19, T - 24S, R - 37E; Lee County, New Mexico
		SPUD DATE: 11/06/93 TD 3750 KB 3,304' DF INT. COMP. DATE: 02/06/94 PBTD 3365 GL 3,294'
		GEOLOGICAL DATA
Surface Csg		ELECTRIC LOGS: CORES, DSTS or MUD LOGS; GR-DLL-MSFL (11-11-93 Halliburton) GR-CSL (11-12-93 Halliburton)
Hole Size: 12 1/4 in		GR-SDL-DSN-CSNG (11-12-93 Halliburton) GR-CSL (11-12-93 Halliburton) GR-SDL-DSN-CSNG (11-12-93 Halliburton) GR-CCL (11-17-93)
Csg. Size: 8 5/8 in		
Set @: 400 ft		HYROCARBON BEARING ZONE DEPTH TOPS:
Sxs Cmt: 250 Circ: Yes		Yates @ 3003' 7-Rivers @ 3230' Queen @ 3587'
TOC @: surf		CASING PROFILE
TOC by: circ		SURF 8 5/8" - 24#, WC-50, ST&C set@ 400'. Cmt'd w/250 sxs - circ cmt to surface.
2		PROD. 5 1/2" - 15.5#, WC-50, LT&C set@ 3750' Cmt'd w/1050 sxs - circ cmt to surface.
		LINER. None
		CSG. PERFS: OPEN HOLE :
		16-Nov-93 Perf'd Langlie Mattix f/ 3426'-30', 3457'-63', 3483'-97', 3510'-13', 3518'-20', 3629'-33' & 3652'-58'
		w/ 2 spf (78 holes total).
		16-Nov-93 Perf'd Jalmat f/ 3006'-15', 3020'-34', 3037'-39', 3046'-49', 3061'-68', 3071'-74', 3087'-3102', 3110'-12',
		3117'-21', 3132'-41', 3149'-51', 3155'-58', 3168'-70', 3173'-75', 3178'-80', 3210'-17', 3223'-28', & 3277 - 95' w/ 2 spf (218 holes total)
		TUBING DETAIL 2/17/05 ROD DETAIL 2/18/05
		Length (ft) Detail Length (ft) Detail
		0 KB 16 1 1 1/4" x 16' polish rod 2893 92 2 7/8" 6.5#, J-55, 8rd EUE tba, 0 1 1 1/2" x 16' liner
		2893 92 2 7/8" 6.5#, J-55, 8rd EUE tbg. 0 1 1 1/2" x 16' liner 3 1 5 1/2" x 2 7/8" TAC 4 1 1" Pony Rod
		340 11 2 7/8" 6.5#, J-55, 8rd EUE tbg. 925 37 1" D steel rods
		32 1 2 7/8" Super Max Blast Joint 1075 43 7/8" D steel rods
		1 1 2 3/6" SN 925 37 3/4" D steel rods
		4 1 2 7/8" Perf Sub 300 12 1 1/2" steel K Bars 16 1 3 1/2" Mud Anchor 20 1 2 1/2" x 1 1/4" RHR Pump w/ 1 1/4" x 8' GA
		16 1 3 1/2" Mud Anchor 20 1 2 1/2" x 1 1/4" RHR Pump w/ 1 1/4" x 8' GA 3289 btm 3265
		WELL HISTORY SUMMARY
	Yates @ 300	7-Nov-94 Replaced broken 1 1/4" polish rod.
	3006 - 3102' 3110 - 3180' 7.R @ 3230' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. 13-May-99 Replaced 1 1/2" polish rod liner. 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods. pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). pump and rods. PWOP. 11-Dec-04 POOH wirds wump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole, busted 3 joints. PWOP.
	3110 - 3180' 7.R @ 3230' 3210 - 3295' TOC @ 3365	 /-May-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. 13-May-99 Replaced 1 1/2" polish rod liner. 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" K0 rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe nitting. PWOP
	7.R @ 3230' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400° and dumped 35° of cmt on top. PBTD=3365°. Replaced pump & all rod boxes. 13-May-99 Replaced 1 1/2" polish rod liner. 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 its. 1-Mar-04 POOH with rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe nitting. PWOP
	7.R @ 3230' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400	 /-May-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. 13-May-99 Replaced 1 1/2" polish rod liner. 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" K0 rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 its. 1-Mar-04 POOH with rods & pump. Changed out 17 - 7/8" rods. 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe nitting. PWOP
XX	7.R @ 3230' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. -Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubi hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3
Production Csg. ole Size: 7 7/8 in sg. Size: 5 1/2 in	3110 - 3180' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3426 - 3497'	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" K0 rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods, pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). pump and rods, PWOP. 11-Dec-04 POOH with rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Poted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3
Production Csq. ole Size: 7 7/8 in Set @: 3750 ft	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). I pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 33
Production Csq. ole Size: 5 1/2 in Set @: 3750 ft Sxs Cmt: 1050 Circ: Yes	3110 - 3180' 3210 - 3295' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3426 - 3497'	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3
Production Csq. ole Size: 7 7/8 in Set @: 3750 ft Sxs Cmt: 1050 Circ: Yes TOC @: surface	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3
Production Csq. ole Size: 5 1/2 in Set @: 3750 ft Sxs Cmt: 1050 Circ: Yes	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 its. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). I pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3:
Production Csq. ole Size: 7 7/8 in Set @: 3750 ft Sxs Cmt: 1050 Cire: Yes TOC @: surface TOC by: cire.	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced all rods and pump. 27-Jan-97 Repaired rod part. Replaced 11 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400° and dumped 35° of cmt on top. PBTD=3365°. Replaced pump & all rod boxes. or 13-May-99 Replaced 1 1/2" polish rod liner. or 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Ported (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). F pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 33
Production Csq. ole Size: 5 1/2 in Sg. Size: 5 1/2 in Set @: 3750 ft Sx5 Cmt: 1050 Cire: Yes TOC @: surface TOC by: circ. PBTD: 3365 ft	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced all rods and pump. 27-Jan-97 Repaired rod part. Replaced 11 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POCH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. 1-Mar-04 POCH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). I pump and rods. PWOP. 11-Dec-04 POCH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubir hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POCH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POCH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 33
Production Csq. ole Size: 7 7/8 in Set @: 3750 ft Size Cmt: 1050 Cire: Yes TOC @: surface TOC by: cire.	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 11 rods and pump. 27-Jan-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 its. 1-Mar-04 POOH with rods & pump, and tubing. Hydrotest tubing to 7000# - busted 2 joints (found holes in 5th jt above SN). I pump and rods. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3:
Production Csq. le Size: 7 7/8 in sg. Size: 5 1/2 in Set @: 3750 ft Circ: Yes TOC @: surface TOC by: circ. PBTD: 3365 ft	3110 - 3180' 7/-R @ 3230' 3210 - 3295' TOC @ 3365 CIBP @ 3400 3426 - 3497' 3510 - 3520' Queen @ 358	 /-May-96 Replaced / sinker bars, pump, & polish rod. 4-Jun-96 Repaired rod part. Replaced 40 - 7/8" rod boxes and rod pump. 12-Sep-96 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Repaired rod part. Replaced 13 - 3/4" rods. 11-Nov-97 Set CIBP @ 3400' and dumped 35' of cmt on top. PBTD=3365'. Replaced pump & all rod boxes. o' 13-May-99 Replaced 1 1/2" polish rod liner. o' 19-Nov-02 POOH with rods and pump. Changed out rod string and pump to increase production. 23-Nov-02 Parted (box) @ 7/8" KD rod. Did not pull pump. 23-Dec-02 Tally out of hole with tubing string. Hydrotest in hole, busted 5 jts. -Mar-04 POOH with rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 9 - 1" rod boxes due to rod wear. Hydrotest tubin hole. Found 90th joint with hole, busted 3 joints. PWOP. 11-Dec-04 POOH w/ rods & pump. Changed out 17 - 7/8" rods, 29 - 3/4" and 42 - 3/4" rods due to severe pitting. PWOP. 3-Feb-05 Parted 3/4" rod (body break) @ 81th rod. POOH & laid 43 - 7/8" and 42 - 3/4" rods due to severe pitting. PWOP. 17-Feb-05 POOH w/rods & pump. Scan tubing: 1 - Yellow, 12 - Blue, 57 - Green, 23 - Double Green, & 10 - Red. Replaced 3