

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-20495
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Robert H. Hannifin
8. Well Number #1
9. OGRID Number 009974
10. Pool name or Wildcat Wildcat San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		7. Lease Name or Unit Agreement Name Robert H. Hannifin
2. Name of Operator HANSON OPERATING COMPANY, INC.	8. Well Number #1	
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88202-1515	9. OGRID Number 009974	
4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>31</u> Township <u>9 South</u> Range <u>30 East</u> NMPM Chaves County	10. Pool name or Wildcat Wildcat San Andres	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4010' GR		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Recompletion <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/20/2004: Build Location and access roads. MIRU.

01/21/2004: Drill out surface plug to 172'. Circulate.

01/22/2004: Wash heavy mud from 1500' to 2000'. Circulate hole clean to 4200'.

01/23/2004: Set CIBP at 4100' with 35' cement cap. Run logs from 4100' to top of cement at 2200'. Perf 5 holes at 3870'-3875'.

01/26/2004: Acidize perfs at 3870'-3875' with 500 gallons 20% acid. RU swab. Swab test.

01/29/2004: Perf 17 holes at 3282'-3369'. Acidize with 2000 gallons 20% acid. RU swab. Swab test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Garcia TITLE Production Analyst DATE 02/02/2004
Type or print name Carol J. Garcia E-mail address: hanson@dfn.com Telephone No. 505-622-7330

(This space for State use)

APPROVED BY Paul J. [Signature] TITLE PETROLEUM ENGINEER DATE MAR 02 2004
Conditions of approval, if any: