## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	
DISTRICT I  PLOTE CONSERVATION DIVISION 1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	30-025-31424
DISTRICT II MAR 3 1 2011	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III	STATE X FEE /  6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	o. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1. Type of Well:	8. Well No. 238
Oil Well   Gas Well   Other Injector  2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	157,501
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323  4. Well Location	
Unit Letter O : 660 Feet From The South 2610 Fee	
Section 4 Township 19-S Range 38-1	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3606' GR	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	SEQUENT REPORT OF.
DEDECTOR DEMENIALANCER I DILICAND ADARIONA I I DEMENIALANCER	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI Length of test: 15 min	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI Length of test: 15 min	NS. PLUG & ABANDONMENT  IT JOB TITY Test  Trity Test  Trity including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ III. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.	NS. PLUG & ABANDONMENT  IT JOB Trity Test  It including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	NS. PLUG & ABANDONMENT  IT JOB Trity Test  It including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.	PLUG & ABANDONMENT  Trity Test  Trity Test
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	PLUG & ABANDONMENT  Trity Test  Trity Test
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_johnson@oxy.com	PLUG & ABANDONMENT  T JOB  rity Test  x  , including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com	NS. PLUG & ABANDONMENT  TIT JOB  Trity Test  To including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be  COCD-approved  Associate  DATE 03/29/2011  TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion OTHER: Casing Integ  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of test: 03/24/2011  Pressure readings: Initial – 520 PSI; 15 mi n- 520 PSI  Length of test: 15 min  Witnessed: Yes – Mark Whitaker w/NMOCD on site.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com	NS. PLUG & ABANDONMENT  TIT JOB  rity Test  , including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be e OCD-approved  Associate  DATE 03/29/2011

