State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT I Santa Fe, NM 87505	WELL API NO. 30-025-37250
DISTRICT II MAR 3 1 7011	5. Indicate Type of Lease
	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 29
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 626
Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4. Well Location	
	et From The West Line
Section 29 Township 18-S Range 38-	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3646' GR	E Cartonia de Cart
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING
	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	ALTERING CASING PLUG & ABANDONMENT NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEI	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER: Casing Integration Completed Operations (Clearly state all pertinent details, and give pertinent dates)	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any completion or recompletion. that any pit or below-grade tank has been/will be e OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT NT JOB grity Test x, including estimated date of starting any completion or recompletion. that any pit or below-grade tank has been/will be the OCD-approved Associate DATE 03/29/2011
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMELOTHER: OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE MAMOCD TITLE Administrative	ALTERING CASING PLUG & ABANDONMENT Total Price of the p
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OF COMMENCE DRILLING OF COMMENCE DRILLING OF COMMENCE DRILLING OF CASING TEST AND CEMEROTHER: OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of test: 03/24/2011 Pressure readings: Initial – 520 PSI; 15 min – 520 PSI; 30 min – 520 PSI Length of test: 30 min Witnessed: Yes – Mark Whitaker w/NMOCD on site I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT Total Test That any pit or below-grade tank has been/will be that any pit or below-grade tank has been/will be a OCD-approved Associate DATE 03/29/2011 TELEPHONE NO. 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMEROTHER: Casing Integration of CHANGE PLANS OTHER: Casing Integration of CASING TEST AND CEMEROTHER OTHER: CASING TEST AND CEMEROTHER OTHER OTHE	ALTERING CASING PLUG & ABANDONMENT Total Test Total Test Total Test Tes

