State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	A 220 South St. Francis Dr.		WELL API NO. 30-025-05484	
DISTRICT II APR 0.1 21113			5. Indicate Type of Lease STATE X	FEE 7
DISTRICT III HOBBSUCD			6. State Oil & Gas Lease No.	TEE
1000 Rio Brazos Rd, Aztec, NM 87410	* ************************************			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agree	ment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Uni	t /
DIFFERENT RESERVOIR. US 1. Type of Well:	E "APPLICATION FOR PERMIT" (Form C-	101) for such proposals.)	Section 24 8. Well No. 131	
Oil Well	Gas Well Other Ir	njector /	151	
2. Name of Operator		*	9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR I Box 90 Denver City,	TX 79323		10.1001 hame of Whata	Hoods (G/SA)
4. Well Location				
Unit Letter L : 2310) Feet From The South	1315F	eet From The West	_ Line
Section 24	Township 18-S	Range 37	-E NMPM	Lea County
	11. Elevation (Show whether DF, R 3671' GR	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	n or Closure			
1	round Water Distance from a	nearest fresh water well	Distance from nearest s	urface water
Pit Liner Thickness mi				
	heck Appropriate Box to Indicate Na NTENTION TO:		Other Data BSEQUENT REPORT C	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIN	G CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING C	PNS. PLUG & A	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEM	ENT JOB	•
OTHER: High casing repair	X	OTHER:		
13. Describe Proposed or Completed	l Operations (Clearly state all pertinent of	letails, and give pertinent dat	es, including estimated date of	starting any
	103. For Multiple Completions: Attach			
1. Kill well.				
POOH w/injection equipment				
3. Repair leak and clean out if no4. Run back in hole with injection				
5. Test casing and chart for the ?				
6. Return well to injection.				
		Condition of	f Approval: Notify OCD I	Hobbs
Per Underground Injection Cor	ıtrol ProgramManual	office 24 ho	ours prior of running MIT	Test & Chart
11.6 C Packer shall be set with	in or less than 100	-		
eet of the uppermost injection	perfs or open hole.	vledge and belief. I further certi	fy that any pit or below-grade tank	has been/will be
	ıit	or an (attached) alternat	ive OCD-approved	
\mathcal{T}_{α}	1 A Oak	plan	L	J
SIGNATURE UNC	ly Warnoon	TITLE Administrativ	ye Associate DAT	E 03/31/2011
TYPE OR PRINT NAME Mendy	A. Johnson E-mail address:	mendy_johnson@oxy.co	m TELEPHONE NO	806-592-6280
For State Use Only				
APPROVED RY	- alu-	_ TITLE	DA DA	TE 4 <u>-4-2011</u>
CONDITIONS OF APPROVAL IF ANY			•	,