# New Mexico Energy, Minerals and Natural Resources Department

### **Susana Martinez**

Governor

John H. Bemis Cabinet Secretary-Designate

Brett F. Woods, Ph. D. **Acting Cabinet Secretary**  Jamie Bailey Division Director Oil Conservation Division



#### \*Response Required - Deadline Enclosed\*

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

06-Apr-11

**CHEVRON US A INC** 15 SMITH ROAD MIDLAND TX 79705

#### LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

## MECHANICAL INTEGRITY TEST DETAIL SECTION

## **CENTRAL VACUUM UNIT No.146**

30-025-26790-00-00

Active Injection - (All Types)

G-31-17S-35E

**Test Date:** Test Reason:

4/1/2011

**Permitted Injection PSI:** 

Actual PSI:

Test Type:

Special Test Requested Std. Annulus Pres. Test **Test Result:** 

Repair Due: 7/5/2011 FAIL CAUSE:

FAIL TYPE: Other Internal Failure

Comments on MIT:

ATTEMPTED PRESSURE TEST: WELL DID NOT BLEED DOWN ON CASING PRIOR TO

PRESSURE TEST\*\*\*\*OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11\*\*\*\* (SECOND LETTER OF VIOLATION)

#### **CENTRAL VACUUM UNIT No.200**

30-025-32805-00-00

7/5/2011

Active Injection - (All Types)

Permitted Injection PSI:

C-6-18S-35E

Test Date: Test Reason: 4/1/2011

**Actual PSI:** 

Test Type:

Special Test Requested

**Test Result:** 

Repair Due:

Std. Annulus Pres. Test

**FAIL CAUSE:** 

Comments on MIT:

FAIL TYPE: Other Internal Failure

FAILED PRESSURE TEST; CASING WOULD NOT BLEED DOWN PRIOR TO PRESSURE TEST\*\*\*\*OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11\*\*\*\* (SECOND NOTICE

OF VIOLATION)

April 6, 2011 Page 2

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Singerely

Hobbs OCD District Office

COMPLIANCE OFFICER

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI. Dallas. Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



US POSTAGE

CHEVRON USA INC. 15 SMITH ROAD MIDLAND, TX 79705