Submit I Copy To Appropriate District	State of New Mexico	Form C-103
Offic:	Ensury Minanala and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 8824	Energy, Winerals and Natural Resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	COMEONSERVATION DIVISION	30-025-05214 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741 APR 0		STATE FEE X
District IV	Sunta 1 0, 1 (101 07 5 0 5	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NMOBBS 87505	SOCD	
SUNDRY NOTICES AND REPORTS ON WELLS (do not use this form for proposals to drill or to deepen or plug back to a		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		T D Pope 36
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other		8. Well Number 6
2. Name of Operator Celero Energy II, LP		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601		10. Pool name or Wildcat /
Midland, TX 79701		Denton: Devonian
4. Well Location		
Unit Letter D : 660		
Section 36	Township 14S Range 37E	NMPM CountyLea
	. Elevation (Show whether DR, RKB, RT, GR, e	ЯС.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTE		JBSEQUENT REPORT OF:
		ENT JOB
OTHER:	OTHER:	
	SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
	perf 2 JSPF from 12104' to 12128', 12148' to 12	2178', 12216' to 12246' and 12325' to 12413'
6/12 - 8/6/10 - Ran CBL & TOC @ 8 CaC12 plus 102 sx Class C w/2% Ca TAC @ 11,920'.	705' & BOC @ 10,050'. Csg leaks @ 1080-174 C12. Fell out of cmt @ 1440'. Csg leaks @ 748	40'. Sqzd w/150 sx Class C w/6% gel & 2% 84-8754'. Sqzd w/200 sx Class C w/6% gel. Set
1/12 -1/17/11 - POOH w/tbg. Unset	ΓΑC. PU 1- jt 2 7/8" tbg, x-over, 6" OD spiral	mill, x-over, 2- 3 ¹ / ₂ " DC's, x-over, 6 Std 2 7/8"
tbg, tag @ 440'. Mill to 445'. TIH to 104'. RIH w/ 5.75 OD gauge ring & ju @ 12,030'. RIH & dump bail 10' cmt	31 jts in @ 1,034'. POH w/ tbg & DC's. RIH w/ unk basket to 12,070'. RIH w/ 7" CIBP w/ Carb	/ x-over, 2nd 6" mill, x-over, 379 ½ jts tbg to 12, bide slips. Tie into CBL dated 6/12/10. Set CIBP
* Continued on attached sheet		
	D' Balance D Au	······································
Spud Date:	Rig Release Date:	
	_	
I hereby certify that the information above	e is true and complete to the best of my knowle	edge and belief.
. /		
SIGNATURE SUSA	TITLE Regulatory Analyst	DATE 03/08/2011
Type or print name Lisa Hunt	E-mail address: <u>lhunt@celeroe</u>	energy.com PHONE: (432)686-1883
For State Use Only	> /	
APPROVED BY:	tITLE START I	VAR DATE 4-11-2011
Conditions of Approval (if any)		
\sim		

4

T D Pope 36 #6 - C103 Continued

<u>1/18/11</u> - TIH w/ 379 jts. Tag @ 12,012' w/ 6 pts, raise tbg to 11,997'. Pump FW w/ soap, 380 bbls gone, Pump 3.5 BPM @ 480# psi. Tbg psi broke back to 100# psi, csg on slight vacuum, pumped a total of 520 bbls. Never broke circ. RIH & tag @ 12,029' w/ 380 jts + 2' w/ 6 pts. Raise tbg to 11,997'. Close BOP & tbg. Csg has slight blow, shoot fluid level, 9784' csg, 9998' tbg. Spot 2 sx sand on CIBP.

<u>1/19/11</u> - RIH w/ 7" CIBP 10,000# differential, tie into CBL dated 6-12-10, CIBP @ 11,965'. POH w/ setting tool, FL @ 9500'. Dump bail 15' cmt on CIBP @ 11,965'. RIH w/ 7" HD pkr, 342 jts 2 7/8" tbg to 10,880'. Leave pkr swinging.

<u>1/20/11</u> - TIH w/ pkr & 374 jts in hole, set pkr @ 11,894'. RU on tbg, load w/ 52 bbls, psi up on CIBP to 500# psi, 15 increments to 3000# psi, no bleed off in 30 min. Release pkr & pump fresh soapy wtr @ 2.5 BPM to break circ. Broke circ w/ 350 bbls gone. Recovered 15 bbls oil, pumped a total of 520 bbls. POH w/tbg & pkr.

1/25/11 –RIH filling up every 20 jts to 7000' then filled up every 10 jts. Ran 213 jts of 5 1/2" ULT-FJ. Liner present depth 8969'.

1/26/11 - Continue PU 5 ½" ULT-FJ, TD 11,943'. Csg. breakdown: 20# suface-1226.83' (29jts) (20# Ext.coated 1226.83'-1746.47'), 20# 1746.47'-4012.54' (54jts),(20#, x/o, 20# box 17# pin), 17# 4012.54'-9057.58' (20#, x/o, 17# box 20# pin), 20# Ext.coated 9057.58'-9624.34' (20#, x/o, 20# box 17# pin), 17# 9624.57'-11,033.15'(34jts), (20# x/o, 20# pin 17# box), 20# 11,033.15'- 11,924.57'(21 jts),(shoe @ 11941.50' w/ k.b.), float collar @ 11853.68'. Circ btms up, 348 bbls. Lead 225 sx class starbond "C" + .1% C-51+.5% FL-10+.65%C-11+.25%C- 45+2%Salt+.25%R-38+.25%C-20. Tail 175 sx 50/50/2"H"+2%Gel+.25%C-12 +,2%C-11+3%Salt+.25%R-38. Lead wt.12.5, 10.02 gal./sx. Tailwt. 14.20, 5.81 gal/sx. WOC. TOC 5900'.

1/27/11 - NDBOP, set slips, cut off, NU. Tag float collar @ 11,950'.

<u>1/28/11</u> - Drl out float collar, shoe & cmt. Circ. to clean. Lost returns after drlg cmt to **11**,965'. Pre mix mud, pumped 900 bbls w/ 2 sweeps of low loss, and total of 4 sweeps. Could not get returns. Build volume to new mud specs, 45 vis, 30#/bbl, 8.6 - 9.6 weight.

<u>1/29/11</u> - Pump 200 bbls of mud down BS. SD for 1 hr. Pumped 950 bbls of mud down tbg w/ 12 polyseal sweeps, 4 sweeps of low loss, still no returns. SD to let mud work. TIH to tag & try to circ, Tag @ 11,968'. Still no returns. Drl to 12,030'.

<u>1/31/11</u> - Mix LCM 150 bbls, pump DP cap w/ FW. SD 2 hrs. Pump pill #2, wait 2 hrs. Try & break circ & drl CIBP ¼ - 0 returns, lost approx 210 bbls in 2.5 hrs. Pump 3rd pill, clear cap w/ FW. SD 2 hrs. Try & break circ, 0 returns. Drl to 12,462'.

2/4/11 - Pump 150 bbls of wtr down w/ no returns. Jetting well @ 100 scf per hr, 375# psi on drill pipe. Jetting well @ 100,000 scf per hr w/ no returns.

<u>2/5/11</u> - RIH to 9816', pumped N2 @ 1 MCF per min, 500# psi on DP. Good returns for 1 ½ hrs. RIH to 10,845', pumped N2 @ 1 MCF per min, 650# psi on DP w/ good returns. Jetting on well @ 1 MCF per min w/ returns dropping off.

<u>2/6/11</u> - Bit @ 9865', pump 60,000 SCF per hr, ¼ ret, bleed DP down. Got back a total of 8 bbls. TIH w/ 32 stds. Bit @ 11,865', pump nitrogen @ 1000 SCF per min, 60,000 per hr, total 35 bbls back. Bleed down DP. TIH w/ 7 stds, bit @ 12,462'. Install inline string float valve. Bring nitrogen to surface, 1500# psi on DP. Inline string valve did not hold, bled down tbg.

<u>2/7/11</u> - Install float valve @ 12,462', bring nitrogen to surface. Drill & C/O from 12,462'-12,665' SCF from 1000-1600 per min returns staying 35-40 bbls per hr. Stop jetting nitrogen, bleed down DP.

2/9/11 - Bring nitrogen to surface @ 1000 SCF a min, took approximately 350,000 SCF total @ 12,462'.

<u>2/10/11</u> - Bring nitrogen to surface @ 12,632', 1100 SCF/min, 49 bbls recovered. Jetting & milling from 12,632' to 12,681', 1100-1200 SCF average of 33 bbl/hr recovered. Mill hanging up. POH to 12,462'. TIH to top of window. Tag @ 12,530', 1300 SCF, 30-35 bbl/hr recovery. Jet & mill to 12,667'. Was not able to get back to 12,681'.

Page 1

<u>2/11/11</u> - Spot 500 gal of 15% HCL. Flushed lines w/ 13 bbls of brine, displace w/ nitrogen. Pulled up 25', wait for 15 min for acid to work. Began nitrogen @ 1300 SCF/hr 105 RPM. Hole dragging, no returns. Jet & mill w/ nitrogen from 12,672' to 12,674'. Lost nitrogen pressure & regained no returns. Continued pumping nitrogen & wait on live oil. Spot 120 bbls of oil & then fluid drill putting 4-8 pts on mill rotating @ 60-105 RPM. Mill from 12,674' to 77'.

2/12/11 - TOH w/ 80 stds. Total of 160 stds & a single left 83 jts in hole (2607'). Top of fish @ 10,069'. TIH w/ 4 5/8" overshot & 3 7/8" grapple w/ pack off. Latch on fish @ 10,069', pulled 90,000 over string wt.

2/13/11 - Run free point 10,132', 100% free. 12,625' taking wt but 100% free. Mill @ 12,674', back off @ 10,132'.

2/15-2/21/11 - Drl from 12646' to 12807'.

2/22/11 - Circ. Pump acid in 3 - 500 gal stages.

3/3/11 - ND MV, NUBOP. RIH w/ 5 1/2" TS bridge plug, 245 jts 2 7/8" 6.5# L-80 8rd tbg. Set TS bridge plug @ 8000'.

3/4/11 - RIH w/ GR/CCL/CBL, log from 1520' to 700'. TOC @ 1030'. RIH w/ overshot & tbg, latch onto TS bridge plug, release BP.

<u>3/11/11</u> -Acdz 5 ½" 17# & 20# csg. Acdz Devonian perfs @ 12,104' – 12,413' & OH KOP 12,474' w/ 60,000 gals of 15% gelled HCL acid using 100- 7/8" 1.3 SP GR Bio balls & 7,500# Coarse Rock Salt as a diverter in 3 stages of 2,500# blocks mixed 1# per/gal in 10# brine. Max = 1890 psi, Avg = 1295 psi, Max rate = 35.5 BPM, Avg rate = 25.3 BPM, ISIP = vacuum.

3/18/11 - RIH w/ a total of 378 jts of 2 7/8" tbg, set 2 7/8" x 5 ½" Model B TAC w/ carbide slips (45K shear), 2 7/8" x 2.32 L-80 stinger @ 11,900'. POH w/ all tbg.

<u>3/23/11</u> - PU Wood Group sub pump as follows: 1- Smartguard sensor, 2- TR4 120 Hp 1295V 59A motors re-rated to 180 Hp 1505V 79A, 2- TR4 98L seals, 2- TR4 RGS intakes, 1- TD Grinder CMP pump – 8 stages, 6- TD 1750 pumps – 658 stages

1- 2 3/8" Std SN, x-over, 289 jts of 2 7/8" 6.5# L-80 8rd tbg (9168.90'), x-over, 82 jts of 2 7/8" 7.90# PH-6 tbg (2508.12'). Splice lower pigtail into new #2 flat lead cable, land donut into seaboard WH. WIR – 110,000.

<u>3/24/11</u> - Build new WH & tie in flowline. Check rotation, start pump up @ 58 Hz, pumped up in 30 min. RDMO. Return well to production.