Submit 3 Copies To Appropriate District State of New Me Office Energy Minerals and Nets	1 70
Office District I 1625 N. French Dr., Hobbs, NM 87240 Energy, Minerals and Natu	WELL ADINO
District II OIL CONSERVATION	N DIVISION 30-025-06192
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Fra	ancis Dr. 5. Indicate Type of Lease
Santa Fe. NM 8	77505 STATE X FEE \(\square\)
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	OR PLUG BACK TO A COMPANY A 20
1. Type of Well: Oil Well	8. Well Number
2. Name of Operator	#002 9. OGRID Number
CIMAREX ENERGY CO. OF COLORADO / ATIN: ZENO FAR	1
3. Address of Operator	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	EUMONT; MONUMENT, GRAYBURG, SA.
4. Well Location	
Unit Letter J : 2310' feet from the SOU	Ine and 2100' feet from the EAST line
Section 20 Township 20S	Range 37E NMPM County LEA
Section 20 Township 20s Range 37E NMPM County IEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3524' - GL	
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well * Distance from nearest surface water *	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material * NONE WITHIN 1,000'.	
12 Chook Annuamiete Day to Indicate Nature (CN 4) D	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF:
	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
04/17/11: SET 4-1/2" CIBP @ 3,650'; PUMP A 40 SX. CMT. PLUG @ 3,650'-3,250'(CALC.); CIRC. WELL W/ PXA	
MUD; PERF. X SQZ. A 35 SX. CMT. PLUG @ 2,660'; WCC X TAG TOP OF CMT. PLUG @ 2,420'. 04/18/11: MIX X PUMP A 20 SX. CMT. PLUG @ 2,420'; WCC X TAG TOP OF CMT. PLUG @ 2,287'; PERF. X SQZ. A 40	
SX. CMT. PLUG @ 1150'; WCC X TAG CMT. PLUG @ 1,120'; PUMP A 30 SX. CMT. PLUG @ 1,120'; WCC.	
04/19/11: TAG CMT. PLUG @ 819'; PERF. X CIRC. TO SURF. A 110 SX. CMT. PLUG @ 270'-3'; DIG CUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INSTALL DRY HOTE MARKER Approved for plugging of Well bore only.	
	Liability under bond is retained pending receipt
WELL PLUGGED AND ABANDONED 04/19/11.	of C-103 (Subsequent Report of Well Plugging)
I hereby certify that the information above is true and complete to the best of my knowledge and the linkful further service that any pit or below-grade tank has been will be constructed or closed according to NMOCD guidelines X, a general permit or in (attached) atternative OCD-approved plan	
SIGNATURE TITL	DATE
Type or print name DAVID A. EYLER	ail address: deyler@milagro-res.com Telephone No. (432) 687-3033
For State Use Only	
APPROVED BY STATE 4-27-201	
Conditions of Approval, if any:	