Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	IN ADHICONSERVATION DIVISION	30-025-04079
District III	CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV MAY 0 4	Conto Eo NM 97505	STATE FEE .
District IV MAY U 4	2011 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 HOBBS	eacii)	
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	TION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA Unit Blk. 8
PROPOSALS.)	ias Well Other TA'd	8. Well Number 11
	ias weii 💋 Other I A d	
2. Name of Operator		9. OGRID Number
Apache Corp.		873
3. Address of Operator PO box Drawer D Monument NM 88	2245	Eunice Monument G/SA
	3203	Eunice Wollument G/SA
4. Well Location		
Unit LetterK:	1980feet from theSouth	line and1980feet from the
west line		<i>C</i>
Section 26	Township 19S Range 36	E NMPM Lea County
Section 20	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
11. Elevation (Snow whether DR, RRB, RT, GR, etc.)		
b		
10 (1 1 4	' D I. II NI-4 CNI-4:	D O/1 D - / -
12. Check Ap	opropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INT	ENTION TO:	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERI		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
	MULTIPLE COMPL CASING/CEMEI	NT JOB 📙
DOWNHOLE COMMINGLE		
OTUED. Fidead TAId at	OTHER.	
OTHER: Extend TA'd st	atus	ud aiva mantinant datas insludina astinasta data
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recor	npietion.	
Will make in Conday's total and make	and the engine to 520 mai for 22 minutes	~)
Will move in Gandy's truck and pressure the casing to 520 psi for 32 minutes. $(198.6x)$		
		on of Approval: Notify OCD Hobbs
	office 2	4 hours prior of running MIT Test & Chart
Spud Date:	Rig Release Date:	
Space Bace.	Rig Release Bate.	
I hereby certify that the information at	pove is true and complete to the best of my knowled	ge and belief.
\bigcirc		
()/()/()	_	
SIGNATURE (1)		
	TITLE_Instrument Tech	DATE
T	-	
Type or print nameJim Ellison_	TITLE_Instrument Tech E-mail address JD. Ellison@ apa	
Type or print nameJim Ellison_ For State Use Only	-	
For State Use Only	E-mail address JD. Ellison@ apa	checorp.com PHONE: 441-7734
APPROVED BY:	-	
For State Use Only	E-mail address JD. Ellison@ apa	checorp.com PHONE: 441-7734