	Submit 1 Copy To Appropriate District Office	State of New	Mexico	Form C-103
	District I	ECE ang Minerals and	Natural Resources	October 13, 2009
	1625 N. French Dr., Hobbs, NM 88240	the state of the state of	WE	ELL API NO. 025-26169
-	District II 1301 W. Grand Ave., Artesia, NM 8821MAY 0 PL CONSERVATION DIVISION District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 874HOBBSUCU Santa Fe, NM 87505		ION DIVISION $\frac{30-7}{5}$	Indicate Type of Lease
-			Francis Dr.	STATE FEE
	District IV	BBSOCD Santa Fe, NI	M 87505 6. s	State Oil & Gas Lease No.
	1220 S. St. Francis Dr., Santa Fe, NM 87505			IB-1428
Γ		CES AND REPORTS ON WI	ELLS 7. I	Lease Name or Unit Agreement Name
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		OR PLUG BACK TO A	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			te 'U' Gas Com
	1. Type of Well: Oil Well	Gas Well Other	8. 7	Well Number 2
7	2. Name of Operator		9. (OGRID Number
	Apache Corp.		000	495
	3. Address of Operator	00075		Pool name or Wildcat
	PO box Drawer D Monument NM	88265	Eun	ice Yates 7 Rivers Queen
4	4. Well Location		•	
	Unit LetterC	:990feet from the	Northline and	d feet from the
Westline				
77.000	Section 32	Township 19		NMPM Lea County
		11. Elevation (Show whether	r DR, RKB, RT, GR, etc.)	
		;		
	12 Classia A		ta Nistana a CNI d' D	. O. D.
	12. Check A	Appropriate Box to Indica	te Nature of Notice, Repo	ort or Other Data
	NOTICE OF IN	TENTION TO:	SUBSEC	UENT REPORT OF:
ı	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
-	TEMPORARILY ABANDON 🛛 🗒	CHANGE PLANS	COMMENCE DRILLING	
I	PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
Į	DOWNHOLE COMMINGLE			
(OTHER:	П	OTHER:	
		leted operations. (Clearly state		pertinent dates, including estimated date
	of starting any proposed wo	rk). SEE RULE 19.15.7.14 N	MAC. For Multiple Completi	ons: Attach wellbore diagram of
	proposed completion or reco	ompletion.	F	
				()
w	/ill MIRII Basic Energy and pull 89) joints of tubing and seat ninn	el Pun in and set CIRD at abo	out 2950' Load with packer fluid chart
	id test.	r Joints of tubing and scat inpp		·
			To	Pert @ 2999'
			•	
	·			
	Rule 19.15.25.14		•	
Set	CIBP, RBP or Packer within 100 feet of some of the common	of uppermost si for 30 minutes with		
pen a pr	ressure drop of <u>not greater t</u> han 10% over	er a		
	minute period.			of Approval: Notify OCD Hobbs
			office 24 r	nours prior of running MIT Test & Chart
Sn	oud Date:	Rig Releas	o Doto:	
Sμ	dd Date.	Kig Keleas	de Date:	
Ιh	nereby certify that the information a	hove is true and complete to t	he hest of my knowledge and l	haliaf
	ereby certify that the information a	bove is true and complete to the	ne best of my knowledge and	bener.
	0000			/
SI	GNATURE S	TITLE In	strument Tech	DATE 5-4-11
m		_		
•	vpe or print nameJim Ellison	_	ress JD. Ellison@ apachecorp	o.com PHONE: 441-7734
•	ppe or print nameJim Ellison or State Use Only	_		<u>.</u>
Fo	· ·	E-mail add		/
Fo	or State Use Only	_	ress JD. Ellison@ apachecorp	