Form 3160-400 (August 2012 New Mexico Oil Conservation Division, District 1625 N. French Drive ORM APPROVED UNITED STATES OMB No. 1004-0137 DEPARTMENT OF THE INTERIOR Hobbs, NM 88240 Expires: July 31, 2010 5. Lease Serial No. **BUREAU OF LAND MANAGEMENT** NM0558287 SHINDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No Oil Well Gas Well Other Morgan A Federal #5 2. Name of Operator Ridgeway Arizona Oil Corporation 9. API Well No 30-041-10416 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) 3a. Address Chaveroo-San Andres 432,687,0303 200 N. Loraine, Suite 1440, Midland TX. 79701 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Roosevelt Co. NM 1980 FSL 1980 FEL J-27-07S-33E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Deepen Production (Start/Resume) Acidize ✓ Notice of Intent ▼ Well Integrity Fracture Treat Reclamation Alter Casing Casing Repair New Construction Recomplete Other Subsequent Report I Temporarily Abandon Plug and Abandon Change Plans Convert to Injection Plug Back Water Disposal Final Abandonment Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) MIRU PU/POOH w/down hole equipment RIH w/bit/scraper to TD - check for fill - clean out as needed RIH w/RBP to 100 ft above top perf. to test casing integrity If casing does not test - spot leak/perform cement squeeze/drill out If casing tests - Remove RBP/RIH w/tubing/packer - circulate packer fluid Call BLM to witness MIT (8 5/8, 24# to 370' / 4 1/2, 9.5# to 4438 - perfs-4218-4287 - TD @ 4438 - PBTD-4369) Second Run Ticket For Load Of Oil From Lease NM-0558287 Was Due MAR 02 2011! Well No. 1-Morgan B Federal Ceased Production In Paving Quantities After NOV 2010 Lease NM-0558287 Will Terminate If Production In Paying Quantities MAY 27 2011 ending Is Not Established By MAY 27 2011!

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Andy Chalker

Title Operations Manager Date 04/08/2011 Signature OR RECHIR SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon (65-12-60// Tany department or agency of the United States any false, Title 18 U.S.C. Section 100 Dans Tive 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully fictitious or fraudulent statements of representations of any matter within its jurisdiction.

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call (575) 627-0205 or after office hours call (575) 420-2832.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)